- Ne	rm 3160-5 ovember 1983) ormerly 9-331)		UI ED STA MENT OF TH AU OF LAND MA	ie inter	ALC: N	SUBMIT IN (Other instr verse side)		ATE.	Bu Ext 5. LEASE	dia approved dget Burcat dires Augus DESIGNATION 02127-B	1 No. 1004 st 31, 1985	5	
	SUNE (De not use this fo	ORY NO	TICES AND R	EPORTS eepen or plug T-" for such	ON back to proposal	WELLS a different r s.)	eservoir.		6. IF IN	DIAN, ALLOTT	EE OR TRIBE	NAME	
1. 2.	OIL GAS WELL WELL	TELL WELL OTHER Salt Water Disposal Well							7. UNIT AGREEMENT NAME Lea Unit 8. Fabm or least name				
3.	Marathon Oil Company								Lea Unit 9. WBLL NO.				
4.~	P. O. Box 552, Midland, Texas 79702 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface								SWD NO. 2 10. FIELD AND POOL, OE WILDCAT Lea				
	1625' FSL and	330' FW	L of Section	12					80	T., B., M., OR RVET OR ARE	A		
14.	PERMIT NO.		15. ELEVATIONS (S GR 3659'			, etc.)			Sec 12. COUN	. 12, T- TY OR PARIS	-205, R-	-34E	
16.		Check A	······	RT 3 o Indicate 1		of Notice.	Report		Lea her Dat		New 1	Mexico	
	Check Appropriate Box To Indicate Nature of Notice, Report, or Ot NOTICE OF INTENTION TO: BUBBEQUE												
17.	TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) DESCRIBE PROPOSED OR C proposed work. If w nent to this work.) •	X	PFLL OR ALTER CASE MULTIPLE COMPLETE ABANDON® CHANGE PLANS SRATIONS (Clearly Stationally drilled, give a		nt detail ations an	· ompre	RATHENT ACIDIZIN Report tion or R	results o	ion Repor	REPAIRING ALTERING (ABANDONME completion t and Log fo estimated da r all marker	OD Well	ng any s perti-	
	On April 22, 1986, an annulus pressure test was conducted on the No. 2. The 4 1/2" tubing X 7" casing annulus would not hold pree Marathon plans to pull out of the hole with the 4 1/2" tubing an tubing will be inspected for defects while it is being pulled. found to be defective, it will be repaired and run back in the h injection packer. The packer will be set and the 4 1/2" X 7" tested. If no defect is found in the tubing, a 7" retrievable b will be run in the hole and the 7" casing will be tested for a 1 found it will be repaired by squeeze cementing. After drilling 4 1/2" tubing and injection packer will be run in the hole. The and the annulus test will be rerun.							essure. Therefore, nd packer. The If the tubing is hole with a redressed annulus will be bridge plug and packer leak. If a leak is out the cement, the					
					1					Ntir Gens U	لا تصال	<i>y</i>	
				· · · · · · · · · · · · · · · · · · ·		•			JU	JN 121	986		
				- 1					-0533	S, NEW	MEXIC	2	
			1										

18.	I nereby certify that the foregoing is true and correct				
	SIGNED 20 3 Holm	TITLE_	Operations Superintendent	DATE	June 10, 1986
	APPROVED BY A Coll (Collarum and Conditions of APPROVAL, IF ANY:	MTLE .	AREA MARAN CARLEAD R	DATE	6-1984

*See Instructions on Reverse Side