

C CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Free ☐
5. State Oil & Gas Lease No.	
B-3464	
7. Unit Agreement Name	
8. Farm or Lease Name	
New Mexico "P" State	
9. Well No.	
4	
10. Field and Pool, or Whichever	
Eunice Monument Grayburg	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒	G/S WELL ☐	OTHER ☐
1. Name of Operator		
Texaco Inc.		
2. Address of Operator		
P. O. Box 728, Hobbs, NM 88240		
3. Location of Well		
UNIT LETTER	I	1654
FEET FROM THE	South	LINE AND 330
FEET FROM	East	THE LINE, SECTION 24
TOWNSHIP	19S	RANGE 36E
N.M.P.M.		

15. Elevation (Show whether DF, RT, GR, etc.)
3686' GR

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE PULC 1103.

- 1) MIRUPU. Pull rods and pump. Install BOP. TOH w/2 7/8" tbg. @ 3924'.
- 2) TIH w/4 3/4" bit, bull-dog bailer, and 2 7/8" workstring. Tag PBTD @ 3944'. Drill out baffle plate and casing shoe @ 3945'. Dump 2% KCL water down tbg.-csg. annulus, then stroke bailer to clean up hole. With bit, drill 5' of formation to TD 3950'. Stroke bailer until open hole is clean. TOH w/bit.
- 3) TIH w/2 7/8" workstring. Lower to 3949'. Acidize open hole @ 3945-50' w/1500 gal 15% NEFE acid and 1/2 drum Checker-Sol mutual solvent. Pump @ 1/2 BPM, 100#. Flush w/2% KCL water.
- 4) Raise tbg into csg. Remove BOP. TIH w/pump & rods. POB. RDP.
- 5) Test production.
- 6) If production is not satisfactory, MIRUPU AND TOH w/rods, pump, and tbg.
- 7) TIH w/4 3/4" bit and bull-dog bailer. Drill open hole an additional 10' to TD 3960'. TOH.
- 8) Run GR-CNL from TD 3960' up into csg.
- 9) TIH w/2 7/8" workstring. Lower to TD and acidize open hole w/3500 gal. 15% NEFE acid and 1 drum Checker-Sol mutual solvent. Pump @ 1/2 BPM, 100#. Flush w/2% KCL water.
- 10) Raise tbg into csg. Remove BOP. TIH w/pump and rods. POB. RDP.
- 11) Test production. Evaluate for chemical squeeze of barium sulfate scale.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED JW Browning TITLE District Admin. Supervisor DATE 12/17/86

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE DEC 29 1986

CONDITIONS OF APPROVAL, IF ANY: