Form 3160-5 (August 1999)	UN D STA DEPARTMEND OF TH BUREAU OF LAND MA	IE INTERI		N.M. OI	، C ا	Divi	Siogo	RM APPROVED B No. 1004-0135 s November 30, 2000		
SUND Do not use abandoned	DRY NOTICES AND RE this form for proposals well. Use Form 3160-3 (PORTS O	IN WELLS	1625 N. Hobbs, ^{r an}	NM 8	8240	89889	No. MA-104724 Martine Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side							NA			
1. Type of Well			Unrevers	e side		7. If Un	it or CA/	Agreement, Name and/or No.		
Oil Well Gas Well Other							NA			
2. Name of Operator						8. Well Name and No.				
Chesapeake Operating, Inc.						We	st Te	as Unit 922		
3h Phone No. 6 18496						9. API Well No.				
$ = \nabla \mathbf{A} \mathbf{A} \mathbf{A} \mathbf{U} \mathbf{U} \mathbf{U} \mathbf{U} \mathbf{U} \mathbf{U} \mathbf{U} U$						30-025-29900				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FNL & 1650' FWL							10. Field and Pool, or Exploratory Area			
"F" Sec 9-20S-33E						Teas-Yates Seven Rivers, Wes 11. County or Parish, State				
12. CHECK AL	PPROPRIATE BOX(FS)		TE MATT			Lea	Co.,	NM		
TYPE OF SUBMISSION	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
	TYPE OF ACTION									
Notice of Intent		Deepe		Product	ion (Start/F	(esume)	D w	aler Shut-Off		
D Subconnet D	Alter Casing		re Treat	🗋 Reclam		,		ell Integrity		
Subsequent Report	Casing Repair		construction	Recomp				^{ther} Perf & Frac		
Final Abandonment Notice	Convert to Injection	Plug al	nd Abandon	Tempor	arily Aban	don		rent a riac		
 3) Perf Yates "3" 32 casing gun w/2 SF 4) RIH w/plug & pkr, NEFE acid across 20 ball sealers t max pressure 46000 5) Isolate Yates "1" & maintain rates 6) POOH w/plug & pkr 3201-3275' with 30 to 20 BPM, max pro- 7) Flowback frac job. 	<pre>imp, rods & tubulars, per picking up workstr 251', 53', 71', 73' & 2F, 42" hole, 60° phas test tools at ± 3300 new perfs, set pkr at hroughout job. Mainta psi 3092-3147' & acidize to 6 BPM to achieve , RIH w/pkr to ±3180' 0,000 gal gelled borat essure 6000 psi, wait . RIse pkr, POOH layin swab well to clean up</pre>	<pre>// The '' T</pre>	Yates "2" Plate to C psi. MI s acidize upproaching 1 15% NEF action, ma ate & frac ing 60,000 vernight.	POOH stand 3201-03, 0 BL dated 0 ervice com w/2000 gal g 6 BPM fo cacid. Sp. acid. Sp. acid. Sp. ture the 1 0# 12/20 sa	ing worl 5, 17, 1 5/13/87 pany. Sp same ac r good b ace 30 b 200 psi. Vates "2 and. Mai	19 via pot 15% cid, inje pall acti pall seal	ion, ers			
 I hereby certify that the foregoing Name (Printed/Typed) 	is true and correct			·						
Barbara J. Bale							_			
1			Tile Regulatory Analyst							
Signature Berbarn Ple		Date 08/30/02								
APPR		R FEDERA	L OR STA	TE OFFICE	USE					
proved by (ORIG. SG	D.) DAVID F. GLASS									
nditions of approval, if any pre-atta tify that the applicant hold begal or ich would entitle the applicant to conc	does not warr in the subject	Title ant or lease Office			Date					
le 18 U.S.C. Section 1001 a0447/11D4 ites any false, fictitious 的名称我们的问题。		a crime for an 0 any matter w	y person know	(ingly and will	 fully to ma	ke to any de	partment	t or agency of the United		
GWW										

W. Teas Unit #922 WORKOVER PROCEDURE AFE No. 300567

- 1) MIRU workover unit. POOH w/ pump, rods, and tubulars. Pressure test tubing out of hole.
- 2) RIH w/ bit and scraper picking up workstring to PBTD 3348'. POOH standing workstring.
- 3) Perforate the Yates "3" 3251', 53', 71', 73', and 75', the Yates "2" 3201', 03', 05', 17', and 19' via casing gun w/ 2 SPF, .42" hole, 60 degree phasing. Correlate to CBL dated 5/13/87.
- 4) RIH w/ plug and packer. Test tools at + 3300' to 6000 psi. Move in acid/fracture service company. Spot 15% NEFE acid across new perfs 3201 3275'. Set packer at + 3180' and acidize w/ 2000 gal of same acid. Inject 30 ball sealers throughout job. Maintain rates approaching 6 BPM to achieve good ball action, max pressure 6000 psi.
- 5) Move and test tools at + 3175'. Isolate the Yates "1" 3092 -- 3147' and acidize with 2000 gal 15% NEFE acid. Space 30 ball sealers throughout job. Maintain rates approaching 6 BPM to achieve good ball action, max pressure 6000 psi.
- 6) POOH with plug and packer. RIH with packer to + 3180'. Establish rate and fracture the Yates "2" and "3" 3201 – 3275' with 30,000 gal of gelled borate containing 60,000# of 12/20 sand per the attached treatment schedule. Maintain rates approaching 20 BPM, max pressure 6000 psi. Wait on frac overnight.
- 7) Flowback frac job. Release packer. POOH laying down workstring.
- 8) RIH production tubing. Swab well to clean up hole. Run 1.5" pump and ¾" rod string. PWOP.

Falcon Creek Re Durces, Inc.



3,400' - 4-1/2" Casing, cmt w/900 sx Class cmt to surface, and circ 73 sx R.T. 4

WTU #922