H. W. ANDREWS #15 WORKOVER PROCEDURE AFE NO. 97H28

- 1. MIRU PULLING UNIT. INSTALL 7 1/16" X 3000 PSI WP FE BARTON FULL OPENING FRAC VALVE AND BOP. TOH W/ PRODUCTION EQUIPMENT AND LAY DOWN TBG. REMOVE BOP AND RDMO PULLING UNIT.
- 2. MIRU MAST TRUCK AND ELECTRIC LINE SERVICES. TIH W/ GUAGE RING AND JUNK BASKET TO 3260'. TOH W/ GUAGE RING. TIH W/ CIBP ON WIRELINE AND SET PLUG @ 3250'. TOH W/ SETTING TOOL. MIRU KILL TRUCK. LOAD CSG W/ 77 BBLS OF 2% KCL WTR AND PRESSURE TEST CSG AND CIBP TO 3500 PSI. BLEED OFF PRESSURE AND RDMO KILL TRUCK.
- 3. TIH WITH 4" CSG PERFORATING GUNS WITH HEGS CHARGES, 2 SPF AND 180 DEGREE PHASING. PERFORATE 5 1/2" CSG AT THE FOLLOWING INTERVALS (90' OF PERFS W/ 193 SHOTS):

3048'-57', 60'-62', 67'-71', 77'-81', 84'-87', 90', 96'-98', 3103'-07', 14'-16',32'-38', 52'-76', 82'-87' & 96'-3220'

RDMO ELECTRIC LINE SERVICES.

- 4. MIRU 7 1/6" X 5 1/2" 10,000 PSI GUARDIAN WELLHEAD PROTECTION CSG HEAD SAVER. MIRU HALLIBURTON FRACTURING SERVICES. RU WELLHEAD FOR IMMEDIATE FLOW BACK. ESTABLISH RATE INTO PERFS @ 10 BPM W/ WELLBORE FLUID AND ACIDIZE THE EUMONT PERFS W/ 8000 GALS OF FOAMED 0.6% FERCHECK 15% HCL ACID @ 50 CO2 QUALITY. DIVERT THE ACID W/ 25 7/8" I.3 RCN BALLS PER 700 GALS OF FOAMED ACID AFTER THE FIRST 3200 GALS FOR A TOTAL OF XXX BALLS USED. FLUSH TO THE BOTTOM PERF W/ 3220 GALS OF 100% CO2. SURGE THE BALLS OFF THE PERFORATIONS AND ALLOW BALLS TO FALL TO THE BOTTOM OF THE WELL FOR A MINIMUM OF 30 MINUTES.
- FRACTURE TREAT THE EUMONT PERFS WITH 91,000 GALS OF 60/55 QUALITY 40 # MY-T-GEL CROSSLINKED GUAR GEL FOAM, 200 TONS OF CO2 AND 250,000 POUNDS OF 12/20 BRADY SAND @ 45 BPM DOWN 5 1/2" CSG. QUALITY CONTROL WILL BE MONITORED BY DICKIE LABS. FLUSH THE FRAC TO THE BOTTOM PERF W/ 3220 GALS OF 100% CO2 AND TURN THE WELL AROUND FOR IMMEDIATE FLOW BACK. RDMO HALLIBURTON.
- 6. FLOW BACK WELL TO CLEAN UP SAND AND CO2 FROM STIMULATION. RDMO *GUARDIAN* ONCE WELL HAS CLEANED UP.