

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33551
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	N/A
7. Lease Name or Unit Agreement Name	W.A. WEIR
8. Well No.	10
9. Pool name or Wildcat	MONUMENT/ABO
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3648'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Amerada Hess Corporation
3. Address of Operator P.O. Box 2040, Houston, TX 77252-2040	4. Well Location Unit Letter <u>D</u> : <u>330</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>35</u> Township <u>19S</u> Range <u>36E</u> NMMPM <u>LEA</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3648'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☒
OTHER: RUNNING 5-1/2" PRODUCTION CSG. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

(CONTINUE)

09-14-96: 50/50 POZ + 8#/SX SALT + 1/4/SX C.F. (14.1#, 1.38). TAIL W/125 SX CLASS "H" + .5% HALAD 9 + 6#/SX SALT + 1/4#/SX C.F. (15.6#, 1.25). DISP. W/168 BBLS F. WATER @ 10 BBLS. MIN. FINAL CIRC. W/2100 PSI. BUMP PLUG @ 12:00 A.M. WITH 3600 PSI, DID NOT CLOSE TOOL, WITH 4100 PSI, DID NOT CLOSE TOOL, 4300 PSI CLOSED TOOL. WATCHED FOR FLOWBACK FOR 1 HR. EST. TOP OF CMT. @ 2500'. SET SLIPS & CUT OFF CSG. NIPPLE UP TUBING HEAD & TEST SAME. O.K. RELEASED RIG AND TURNED OVER TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Mike Jumper

TITLE ADM. SUPERVISOR DRILLING

DATE 09-17-96

TYPE OR PRINT NAME MIKE JUMPER

TELEPHONE NO. 713-609-4846

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: