

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-025-33919</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>Bertha Barber</b>
8. Well No. <b>16</b>
9. Pool name or Wildcat <b>Monument Tubb &amp; Abo</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>KB 3570' GL 3554'</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
**Marathon Oil Company**

3. Address of Operator  
**P.O. Box 2490 Hobbs, NM 88241**

4. Well Location  
Unit Letter **K** : **2140** Feet From The **South** Line and **1650** Feet From The **West** Line  
Section **5** Township **20-S** Range **37-E** NMPM **Lea** County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **DHC Tubb and Abo (DHC-2506)** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1/17 MIRU pulling unit. POOH w/rods. ND wellhead. Rel TAC. NU BOP. RIH, tag fill at 6911'. Swab.  
1/20 POOH w/tbg. RIH w/retrieving tool to 5526'. Tag fill at 6931'. Clean out w/foam air to 7100' (top of CIBP). Latch onto RBP, release. POOH w/tbg and RBP.  
1/21 RU pipe testers. Test pkr. Pump 20 bbls 2% KCL. Continue in hole to 7124'. Test tbg. PUH w/pkr, set at 7124'.  
1/22 Pump 4000 gals 15% acid w/40 BS. Swab. Rel pkr. RIH to 7364'.  
1/23 Swab. POOH w/tbg & pkr. RIH w/2 3/8" tbg. ND BOP. Set TAC. NU wellhead.  
1/24 RIH w/pump & rods. Load & test, OK. ND pulling unit.

TAC at 6280'  
SN at 7245'  
Btm of tbg 7312'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 2/1/00  
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY CHRIS WILLIAMS  
TITLE STATE SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: GO