

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name M. B. Weir B
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 7
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>825</u> FEET FROM THE <u>West</u> LINE, SECTION <u>12</u> TOWNSHIP <u>20-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Weir Blinberry, East</u> <u>Monument Tubb, Skaggs Dr</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3569' (DF)</u>	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Triple Downhole Commingle</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIGGED UP. PULL PAKER FROM TUBB STRING.
2. INSTALL CIBP IN TUBB STRING AND CAP W/40' CEMENT.
3. PERFORATE 2 7/8" CASING IN THE DRINKARD STRING W/4-JSPF FROM 6617' - 6629' AND @ 6634', 39', 58', 62', 66', 75', 79', 86', 93', 6706', 09', 29', 47', & 6753'.
4. SET PKR IN DRINKARD STRING @ 6550'. ACIDIZE PERFORATIONS 6617' - 6852' W/ 16,000 GALS LST NEFE 28% ACID, 600# ROCK SALT, & 6300 GALS 2% KCL ACID IN 3-STAGES. FLUSH W/ 10# BRINE.
5. SET RBP IN DRINKARD STRING @ 6570'. SET RBP @ 5650'.
6. PERFORATE BLINBRY STRING W/4-JSPF FROM 6800' - 6810'.
7. CLEAN OUT DRINKARD STRING TO 6810'. LOG WELL. PERFORATE DRINKARD STRING W/4-JSPF FROM 6800' - 6810' AND W/2-JSPF FROM 6426' - 6432'; 6475' - 6484'; 6080' - 6090'; : & @ 6100', 47', 63', 72', 76', FROM 6368' - 6372'; & @ 6380', 90', 92', 94', 6404', 40', 51', 65', 90', 6518', & 6532'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Seay TITLE Asst Dist Mgr DATE 8-17-84

Eddie W. Seay

AUG 21 1984

APPROVED BY Oil & Gas Inspector

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 20 1984

O.C.D.
HOSES OFFICE

8. SET PKR @ 6713'. ACIDIZE PERFS 6368' - 6532' W/6000 GALS 15% NEFE ACID IN 3-STAGES USING 300# ROCK SALT BETWEEN STAGES. FLUSH W/10# GEL BRINE.
9. SET RBP @ 6281' AND PKR @ 5665'. ACIDIZE PERFS 5742' - 6176' W/6000 GALS 15% NEFE ACID IN 3-STAGES USING 300# ROCK SALT BETWEEN STAGES. FLUSH W/10# GEL BRINE.
10. REPERFORATE DRINKARD STRING W/4-JSPF FROM 6800' - 6810'.
11. SET PKR IN BLINEBRY STRING @ 6700'. ACIDIZE COMMINGLE PERFS 6800' - 6810' W/500 GALS 15% NEFE ACID AND FLUSH W/20 BBLs WATER.
12. INSTALL PUMPING EQUIPMENT IN DRINKARD STRING. ON 24 HOUR POTENTIAL TEST, ENDING 8:00 AM, 8-12-84, WELL PUMPED 8 BO & 19 BW. WELL COMPLETED AS TRIPLE DOWN HOLE COMMINGLE, BLINEBRY, TUBB, AND DRINKARD.