

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instruction
verse side)

Budget Bureau No. 1004-0115
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Britt B
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, NM 88240	9. WELL NO. No. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface FNL 660' RNL & 330' FWL Unit A	10. FIELD AND POOL, OR WILDCAT Eunice Monument G-SA
14. PERMIT NO. APL # 30-025-0610100	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 15, T20S, R37E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3562' DF	12. COUNTY OR PARISH Lea
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. MIRU. ND wellhead and NU BOP.
2. Set plug in open hole. Pump 35 sx cement from 3919' to 3550'. Load and circ. hole with 87 bbls mud. TAG SJS
3. Perf 5-1/2" casing @ 1310'. Pump 24 bbls mud to load hole and establish Circ. up annulus. Pump 25 sx cement to spot a plug from 1315' to 1215'. TAG SJS
4. Perf 5-1/2" production casing @ 250'. Pump 10 bbls mud to load hole and establish circ. Pump 45 sx cement to fill up 7-5/8" annulus.
5. ND BOP and cut off all casing strings at the base of the cellar. Erect an abandonment marker.

For further technical information contact Neal Hoover @ 397-5858.

18. I hereby certify that the foregoing is true and correct

SIGNED W.W. Baker W.W. Baker TITLE Administrative Supervisor DATE July 22, 1989

(This space for Federal or State office use)

APPROVED BY Shammy Shaw
CONDITIONS OF APPROVAL, IF ANY:

FOR: CHIEF, MINERAL SERVICES
TITLE

DATE 8-15-89

*See Instructions on Reverse Side