					Form C-103	
Submit 3 Copies To Appropriate District	State of N	New Mexi	co		Revised March 25, 1999	
Office	Ene. بر, Minerals	and Natura	l Resources	WELL API NO.		7
District I 1625 N. French Dr., Hobbs, NM 88240				30-025-06208		
District II	OIL CONSERV	ATION I	DIVISION	5. Indicate Type of	f Lease	
1301 W. Grand Ave., Artesia, NM 88210	1220 South	St. Franc	is Dr.	STATE X	FEE	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		6. State Oil & Ga			
District IV 1220 S. St. Francis Dr., Santa Fe, NM				7. Lana Name or	Unit Agreement Name:	-
87505 SUNDRY NOTIO	CES AND REPORTS OF	N WELLS		/. Lease Name of	Olite Agreement 2 and	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR FLOOD DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Bell Ramsay (NC)	Г-В)	
1. Type of Well: Oil Well 🔲 Gas Well 🕅	Other			8. Well No. 2		-
2 Name of Operator				8. Well No. 2		
2. Theme of op Chevr	ron U.S.A. Inc			9. Pool name or	Wildcat	
3. Address of Operator	Box 1150, Midland, TX	79702		Eumont;Yates-7R	ivers-Queen	
P. O. 4. Well Location	Box 1150, Milliand, 11					
**		d 660 faet fr	om the West line			
Unit Letter M : 660 fee	t from the South line and		on ne west me		T T A Country	
Section 33	Township	205	Range 37E	NMPM	LEA County	
Section 93	10. Elevation (Show	whether DI	R, RKB, RT, GR, 6	etc.)		
	3530' GR Appropriate Box to I	Indiante N	ature of Notice	Report or Other	Data	
11. Check	Appropriate Box to I	indicate N	SU	BSEQUENT RE	PORT OF:	
NOTICE OF I	NTENTION TO: PLUG AND ABANDO	N X	REMEDIAL WC	RK 🛛	ALTERING CASING	
PERFORM REMEDIAL WORK	PLUG AND ABANDO				PLUG AND	
	CHANGE PLANS				ABANDONMENT	
PULL OR ALTER CASING] MULTIPLE COMPLETION		CASING TEST CEMENT JOB			
			OTHER:			
OTHER: 12. Describe proposed or comple	and operations (Clearly	state all per	tinent details, and	give pertinent dates,	including estimated dat	e of
12. Describe proposed or comple starting any proposed work). recompilation.	SEE RULE 1103. For M	Iultiple Con	npletions: Attach	wellbore diagram of	proposed completion of	-
Chevron proposes to P&	A per the attached D	rocedure.				
Chevron proposes to P&	A per une attached p				tion to domonstrate	the
This well is part of the Ne plugging and abandonme	w Mexico "P&A Pilo ent process using high	ot Project" ily compre	conducted by essed sodium be	Benterra Corpora entonite nodules as	s the plugging mediu	m.
	UENT PRA TO PROM	AS				
POST SUBSEQUENT P&A TO RBDMS COMPLIANCE SCREEN						
	N/					
I hereby certify that the informati	on above is true and con	nplete to the	best of my know	ledge and belief.		
I hereby certify that the information	2'		n 1			
SIGNATURE <u><u> </u></u>	ipely	TITLE_	Regulatory C			1148
Type or print name J.K. Riple	y			10	elephone No.(915)687-7	2601
						- 1 C I

_TITLE___

DATE_

Ð

(This space for State use)

APPPROVED BY_____ Conditions of approval, if any:

BENTERRA Corporation Mid-Continent Region

P&A PROCEDURE

Well Name:	Bell Ramsay NCT-B #2
API Number:	30-025-06208
Coordinates:	660' FSL & 660' FWL
S-T-R	33 - 20S - 37E Unit M
County / State:	Lea, NM
Drilled:	1937

Operator:	Chevron
Field:	Eumont
Date:	8/21/01
By:	DCD

Provide 24 hr Notification to NMOCD of Pending Operations

Note: If Chevron has already pulled tbg, proceed to Step 3.

- 1. MI PU. Hold pre-job safety mtg and check 7" csg and 95/8" x 7" annulus for press. RU PU.
- 2. Install BOP. POH & LD 3530' of tbg. Remove BOP, install WH equip & secure well. RD&RPU.
- 3. MI Benterra equip. Hold pre-job safety mtg and spot equipment. Check 7" csg and 95/8" x 7" annulus for pressure.
- 4. ND WH equip and install well control equip.
- 5. Check btm w/ SL , CR @ 3640'. Record FL. Displace wellbore fluids w/ freshwater.
- 6. Insert 7" wiper plug (cored to allow fluid bypass) into csg and push to 2650' w/ slickline.
- 7. Surface pour 23 cu ft of ZONITE to set 100' btm plug from approx 2550 2650'. Set plug in stages, check w/ SL to assure bridges are not occurring and required plug height is achieved. Pour at rate that minimizes potential to bridge. After setting plug, add water as necessary to assure hydration of plug. Remove well control equip and NU WH to secure well.
- Move off location and wait appoximately 48 hours for plug to hydrate. Assure that an adequate fluid level to hydrate plug is maintained.
- 9. MI PU and ancillary equipment for cutting/pulling 7" csg. Hold safety pre-job safety meeting. Check 7" casing and annulus for pressure, RU PU and equipment. Load hole w/ freshwater.
- 10. RU equip to stretch and free-point 7" casing:

If free-point is 100' or more above 95/8" csg shoe at 1255':

- a. Release from csg, set 7" wiper rubber at 1305' and set 135' (30 cu ft) ZONITE plug inside csg from from 1170 1305', across Rustler and the 95/8" shoe. Use pouring precautions as in Step 7 and add water if necessary to hydrate plug.
- b. Set 7" wiper rubber at 375' and cap w/ 10' (2 cu ft) of ZONITE. Cut-off 7" csg at base of FW at 350' and POH LD. Set 100' (44 cu ft) ZONITE plug from 250 350 on top of stub and across freshwater. Use precautions while pouring as in Step 7 and add water if necessary to hydrate plug.
- c. Skip to Step 14 setting top plug.

If free-point is 50' or more below 95/8" csg shoe @ 1255':

- Release from csg, set 7" wiper plug 1325', cap w/ 10' (2 cu ft) of ZONITE and cut-off 7" csg at 1305'. POH LD csg.
- Set 135' (70 cu ft) ZONITE plug from 1170 1305' on top of stub, across Rustler and across 95/8" shoe.
- 11. Check top of plug w/ SL. If necessary, fill casing w/ freshwater.
- 12. Push cored 95/8" wiper plug to 350' w/ slickline.
- 13. Pour 100' (44 cu ft) ZONITE and set plug from 250 350', across FW zone. Set plug in stages using precautions as in Step 7.
- 14. Insert & push 95/8" wiper plug to 30' w/ SL. Fill csg w/ ZONITE to 3' from surface (14 cu ft). Add water as needed to hydrate plug.
- 15. Secure wellbore and RD equip.
- 16. Allow 48 hours for ZONITE to hydrate, remove WH, cut off casings 3' below GL and cap wellbore.
- 17. Install dry hole marker stamped w/ required well identification, 4" OD x 4' above GL.
- 18. Remove all equip and cut deadmen below GL.
- 19. Turn over to Chevron for any surface remediation work.

Estimated ZONITE Requirements:

153 ft³

WELL PLANNING SHEET EXISTING CONFIGURATION

Well Name: API Number: Coordinates: S - T - R County / State: Drilled:	Lea, NM 1937	it M		Operator: <u>Chevron</u> Field: <u>Eumont</u> Date: 7/26/2001 By: <u>DCD</u>
RKB = 8.2 Formation Top Rustler 122 Salt 130 Yates 266 7 Rivers 292 Queen 333	s 20' 204' 35' 29' 75'			16" - 50# @ 38' w/ 60 sx, not circ
Penrose 34	98'			Rustler = 1220' 9 5/8" - 32# @ 1255' w/ 600sx, circ Top of Salt = 1304'
	23/8 tbg @ 3530'		Per	fs: 2690 - 2994' w/ 1 JSPF fs: 3375 - 3480' & 3515 - 3560' w/ 2 JSPF - 22# 10 thrd @ 3654' w/ 200 sx TOC N/A 1 sq w/ 500sx. CR @ 3640'

WELL PLANNING SHEET Proposed P&A

			Operator:	Chevron
Well Name:	Bell Ramsay NCT-B #2		Field:	Eumont
API Number:	30-025-06208 660' FSL & 660' FWL		Date:	7/26/2001 DCD
Coordinates:	33 - 20S - 37E Unit M		Ву:	000
S - T - R County / State:	Lea, NM			
Drilled:	1937			
Replaced 7* casing	at 6' (8/14/96)		16°-50#@38'	w/ 60 sx, not circ
RKB = <u>8.2</u> 5	<u>-</u> EL			
Formation Tops Rustler 122 Salt 130 Yates 266 7 Rivers 292 Queen 337	0' 4' 5' 9' 5'			
Penrose 349	18		Rustler = 1220'	
			95/8" - 32# 8rd @ 1	255' w/ 600sx, circ
		$\langle \rangle$	Top of Salt = 1304' Cut csg @ 1305'	
ZON	ITE Plugs		TOC = Unknown	
3 - 30'	Top Plug			
250 - 350'	FW			
1170 - 1305'	Rustler / Shoe			
2550 - 2650'	Perf Plug			
	23/8 tbg @ 3530'			
	200 kg 2 000		Perfs: 2690 - 2994' w/ 1	JSPF
			Perfs: 3375 - 3480' & 35	515 - 3560' w/ 2 JSPF
			7" - 22# 10 thrd @ 3654	w/ 200 sx TOC N/A
			CR @ 3640', OH sq w/	500 sx
		3840'	TD	