Form 3 160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Oil	Cons. Division
1625 N.	French Dreau No. 1004-0135
Hobbe A	Lean Designarian and Serial No.


DONDING OF BIN	Hobbs,	NM 0557686	
Do not use this form for proposals to drill or	D REPORTS ON WELLS r to deepen or reentry to a different reservoir. PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name	
SUBMIT IN	7. If Unit or CA, Agreement Designation		
1 Type of Well Oil Gas Well Other 2. Name of Operator		8 Well Name and No. SEMU Skaggs B #7	
Conoco Inc	9. API Well No.		
3 Address and Telephone No. 10 DESTA DR. STE. 100W, MIDLAND, TX 7	30-025-06246 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T. R. M. or Survey Description)		Monument Tubb	
1980' FNL & 1980' FWI	11. County or Parish, State Lea, NM		
CHECK APPROPRIATE BOX(s) T	O INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
13 Describe Proposed or Completed Operations (Clearly state all perting give subsurface locations and measured and true vertical department.)	nent details, and give pertinent dates, including estimated date of starting this for all markers and zones pertinent to this work.)*	g any proposed work. If well is directionally drille	

Conoco requests approval to plug and abandon this well, per the attached procedure.

APPROVAL SUBJECT TO
REPERAL REQUIREMENTS AND
SPECIAL STIPULATIONS ATTACHED

Signed Delan Wille Regulat	—— Title Regulatory Specialist		9/10/01
(This space for Federal or State office use) (ORIG. SGD.) ALEXIS C. SWOBODA title Conditions of approval if any.	PETROLEUM ENGINEER	Date	SEP 17 2001

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



SEMU Skaggs B #7

Surface casing: 13-3/8" @ 225' cmt'd to surface

Intermediate csg: 9-5/8" @ 2,855' cmt'd w/ 700 sx, TOC 1,850'

Production csg: 7" 23, 26, 29# csg @ 7,648 cmt'd w/ 1,100 sx, TOC 2,875'
Perforations: Tubb perforations 6,282 – 6,572'; CIBP set @ 6,260'

- 1. Set steel working pit. Flow well down as needed.
- 2. MIRU plugging equipment. NU BOP.
- 3. RIH w/ workstring to CIBP @ 6,260'. Circulate hole w/ 240 bbls mud. Pump 25 sx C cmt on top of CIBP.
- 4. POOH w/ tubing to 4,000' and pump 25 sx C cmt 4,000 3900'.
- 5. Perforate 7" casing @ 2,875' w/ 1-11/16" link-jet gun under lubricator.
- 6. RIH w/ AD-1 packer to 1,300' and squeeze 50 sx C cmt w/ 2% CaCl₂ 2,775 2,875'. WOC and TAG this plug. *Intermediate casing shoe*
- 7. Perforate 7" casing @ 2,500' w/ 1-11/16" link-jet gun.
- 8. RIH w/ AD-1 packer to 2,200' and squeeze 50 sx C cmt 2,500 2,600'. Base of salt
- 9. Perforate 7" casing @ 1,378' w/ 1-11/16" link-jet gun.
- 10. RIH w/ AD-1 packer to 1,100' and squeeze 50 sx C cmt 1,278 1,378'. WOC and TAG this plug. *top of salt*
- 11. Perforate 7" casing @ 275' w/ 1-11/16" link-jet gun.
- 12. RIH w/ packer and squeeze 115 sx C cmt under packer 175 275'. WOC & TAG this plug. **Surface csg shoe**
- 13. Pump 15 sx C cmt 50' to surface.
- 14. Cut off wellhead and install dry hole marker. Cut off anchors and close working pit.

