

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
9. Well No.	
10. Flow and Pool, or Wildcat	
12. County	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>Plug & Abandoned</u>	7. Unit Agreement Name
2. Name of Operator <u>Continental Oil Company</u>	8. Farm or Lease Name <u>Phillips Hooper.</u>
3. Address of Operator <u>Box 460, Hobbs, N.M. 88240</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>O</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>27</u> TOWNSHIP <u>20 S</u> RANGE <u>37 E</u> NMPM.	10. Flow and Pool, or Wildcat <u>Arroyo E-M-E</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOBS ☐
OTHER ☐	OTHER ☐
PLUG AND ABANDON ☐	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up and Pulled Tbg + Pkr. Ran CMT Retainer ON Tbg and set AT 3402'. Mixed 150 SX Class "C" CMT with 2% CACL2. Squeezed Pkts 3502'-3606' with 110 SX Below Retainer and 7 SX Above Retainer, Reversed out 33 SX. Ran Sinker Bar and Tagged CMT AT 3337'. Set Pkr AT 1830' and Tested CSG From 1830' TO CMT Above Retainer TO 1500 PSI, Hold OK. Re-set Pkr AT 1710' and Tested Sq. Brts 1800-01' AT 1750 PSI For 30 min. Hold OK. Tested 5 1/2" CSG Above Pkr TO surface AT 1500 PSI, Hold OK. Set CMT Plugs As Follows: 25 SX class "C" CMT 1830'-1620'; 25 SX class "C" CMT 1300'-1090'; 10 SX Surface Plug 35' to surface. Erected Dry Hole Marker and Restored The Surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Wm. A. Butler</u>	TITLE <u>Assoc. Supv.</u>	DATE <u>10-10-77</u>
APPROVED BY <u>Edith</u>	TITLE <u></u>	DATE <u></u>