

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER		7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Co.		8. Firm or Lease Name A. B. Reeves
3. Address of Operator P. O. Box 1861, Midland, TX 79702		9. Well No. 2
4. Location of well UNIT LETTER <u>D</u> <u>440</u> FEET FROM THE <u>North</u> LINE AND <u>440</u> FEET FROM THE <u>West</u> LINE, SECTION <u>29</u> TOWNSHIP <u>20-S</u> RANGE <u>37-E</u> NMPM.		10. Field and Pool or Wadwell Eumont-Yates Seven Rivers Queen (Pro Gas)
11. Elevation (Show whether DF, hT, CR, etc.) 3517' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Drilled or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/8 MIRU Xpert WS/ Lwr tbq, latch onto Guib Unipkr VI at 3338. Otis WL pull blankline plug from profile nipple at 3336. Relse pkr, poh w/ tbq and pkr. Ran 2-7/8 tbq OE to 3360, circ hole w/ 9-1/2 LB mud laden fluid, POH. Ran (5 1/2 Howco) CIBP on 2-7/8 tbq, set CIBP at 3355, POH w/ 2-7/8 tbq. CRC ran WL dump bailer, dump 4 sxs cmt on CIBP 3323-3355.

11/9 CRC perf 4 sqz holes @ 2845. RIH w/ 2-7/8 tbq open end. Howco spot 25 sxs plug 2845 - 2690, WOC 4 hrs, RIH w/ 2-7/8 tbq, tag top cmt @ 2690. POH w/ 2-7/8 tbq. CRC perf 4 sqz holes 1175, RIH w/ 5 1/2 BKR AD-1 on 2-7/8 tbq, test csg @ various intervals found hole in 5 1/2 csg 90-120' w/ returns to surface out Braden head. Release pkr POH.

11/10 RIH w/ 5 1/2 AD-1 pkr on 2-7/8 tbq, set pkr @ 1101, Howco estb inj rate into squeeze perfs @ 1175, 3 BPM @ 100 psi w/ full returns on 5 1/2 & 9-5/8 csg annulus release pkr & POH w/ tbq & pkr. RIH w/ 5 1/2 cmt retainer set @ 1101. Howco squeeze perfs 1175 w/ 400 sxs class "C" neat cmt, FP 300 psi & holding circ 6 sxs thru Braden head, snap out of retainer & dump 10 sxs on top retainer. POH & lay dwn 2-7/8 tbq NU well head. Howco squeeze hole in csg @ 120' w/ 50 sxs class "C" neat, displaced cmt to 22' FP 100 psi, circ 25 sxs thru Braden head. Cut off well head weld on steel plate in stall dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Sr. Acctnc. Asst.

TITLE Sr. Acctnc. Asst.

DATE 11/14/83

APPROVED BY

TITLE

DATE SEP 2 1985

CONDITIONS OF APPROVAL, IF ANY: