

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

✓ O+2 - NMOCD-P.O. Box 1980 1 - Foreman - CM
Hobbs, NM 88240 1 - WIO's
1 - Engr.-PB 1 - File

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-2690	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dual		7. Unit Agreement Name	
2. Name of Operator Getty Oil Company		8. Farm or Lease Name Skelly G State Com.	
3. Address of Operator P.O. Box 730 Hobbs, NM 88240		9. Well No. 1	
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 30 TOWNSHIP 20S RANGE 37E NMPM.		10. Field and Pool, or Wildcat Eumont (Gas)-Eunice Monument GR-SA	
15. Elevation (Show whether DF, RT, GR, etc.) 3531' DF		12. County LEA	

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> convert to single completion

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit. Install BOP.
2. POH with rods and tubing.
3. GIH w/bit and casing scrapper to 3600'. POH.
4. GIH with retrievable BP. Set BP at + 3600'.
5. GIH w/RTTS packer and set at 3590'. Test BP to 1500#. POH w/packer.
6. GIH with E-Z drill retainer. Set retainer at + 3300'.
7. Squeeze Eumont gas perms 3360-3525 w/150 sxs. class "C" cement w/3#/sx. salt. Reverse out excess cement. POH w/tubing. WOC.
8. GIH w/-6 1/8" bit, drill out retianer and cement to BP. Test squeeze to 200#. POH w/bit.
9. GIH w/retrieving tool and pull BP.
10. GIH with drill collars and 6 1/8" mill. Drill Model "D" packer at 3688'. Work with Model "D" packer until it has been drilled up or pushed to bottom. POH.
11. GIH w/tbg. and jet sub, hydra-jet and clean out open hole section, 3712'-3840'.
12. Spot 500 gals 15% Hcl in open hole section. POH.
13. GIH w/7" model "R" packer and set at + 3700'.
14. Stimulate open hole section, 3712'-3840' per service company's recommendation.
15. POH w/tbg. and packer. GIH w/bit and reverse out any sand and circulate clean. POH.
16. GIH with pump, rods, and tubing. Return well to production.
17. Rig down unit.
18. Test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale R. Crockett TITLE Area Superintendent DATE 3/3/82

APPROVED BY _____ TITLE _____ DATE APR 17 1982

CONDITIONS OF APPROVAL, IF ANY: ONE

Mo AI