

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

101-588

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dual	7. Unit Agreement Name
2. Name of Operator TEXAS PACIFIC OIL COMPANY	8. Farm or Lease Name Sorky
3. Address of Operator P. O. Box 1069 - Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER E , 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 21-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Blinbry & Tubb
15. Elevation (Show whether DF, RT, GR, etc.) 3395' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER Recomplete New Zone <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Upon approval, we propose to recomplete from TA Blinbry Gas to Blinbry Oil and re-stimulate Tubb Oil as follows:

1. Move in, rig up, pull tubing, run retrievable BP @ 5875' w/2 sks. sand on top.
2. Run ret. packer to 5500' and test casing to 3000#. Pull and run packer to 5540'.
3. Squeeze perfs. 5640-50' w/50 sks. cement. Test to 3000#. WOC 24 hrs.
4. Drill out cement to BP. Log to TB.
5. Set packer @ 6175', acidize Tubb perfs. 6225-6313' w/4000 gal. 15% HCl and ball sealers.
6. Frac down 3 1/4" frac tubing w/20,000 gal. gelled brine / 16,000# 20/40 sand and flush with prepared brine.
7. Run lock-set packer to 6175'.
8. Perf. Blinbry Oil zone 5800-6030' w/ 3/8" JSPP. Perfs to be selected from logs.
9. Run ret. packer and ret. BP @ 6100'. Spot 475 gal. acid across perfs.
10. Set packer @ 5660' and acidize w/1500 gal. 15% HCl acid.
11. Frac Blinbry Oil perfs. w/45,000 gal. gelled brine / 40,000# 20/40 sand. Flush.
12. Run dual strings of tubing and BP. Swab to flow and test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by

SIGNED Sheldon Ward TITLE Area Superintendent DATE 5-2-68

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: