NO. OF COPIES RECEIVED		
DISTRIBUTION		Form C-103 Supersedes Old
LANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE	IL # MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.	3 - NM OCC	
	1 - File	5a. Indicate Type of Lease
OPERATOR		State Fee X
OF ERATOR		5. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR	DRY NOTICES AND REPORTS ON WELLS proposals to drill or to deepen or plug back to a different reservoir. cation for permit -" (form C-101) for such proposals.)	
USE **APPLI	CATION FOR PERMIT -** (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL	OTHER-	7. Unit Agreement Name
2. Name of Operator		
Getty Oil Company		8. Farm or Lease Name
3. Address of Operator		S. J. Sarkeys 9. Well No.
-	34	9. Well No.
4, Location of Well	Mexico	1
		10. Field and Pool, or Wildcat
UNIT LETTER P	1980 FEET FROM THE North LINE AND 660 FEET FROM	Drinkard - Tubb
Wast	04	
THE NEBU LINE, SEC	TION 26 TOWNSHIP 21 RANGE 37 NMPM	
		$\Delta M M M M M M M M M M M M M M M M M M M$
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3389 * GL	
Chec	k Appropriate Box To Indicate Nature of Notice, Report or Ot	het Data
NOTICE OF		REPORT OF:
		REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUS AND ABANDONMENT
	OTHER	and an to the
OTHER	OTHER	- CHINE
17. Describe Proposed or Completed	Operations (Clearly state all pertipent details and give portionant details in 1 1	

work) SEE RULE 1903. Pulled short, string and Baker Model D maker Department details, and give pertinent dates, including estimated date of starting any proposed

Pulled short string and Baker Model D packer. Ran Baker retrievable BF and full bore packer. Set BP @ 5915', circulated 23' sand to BP. Set packer at 5611'. Squeezed perforations 5745-5827! with 100 sacks Class "C" cement w/3# salt/sx and 0.5% CFR-2 followed with 50 sacks Class "C" with 7# sand per sack. WOC 24 hours, drilled out cement and tested squeeze with 500# for 30 minutes, no drop in pressure. Perforated additional Drinkard, 6363-6438' with 19 holes. Treated with 3,000 gals. 15% NE and 38 ball sealers. Fraced with 30,000 gals. Poly-Vis and 45,000# 20-40 sand, 1400# salt and 1000# benzoic acid. Swabbed Drinkard to flowing. Perforated Tubb zone 5926-6246' with 35 holes. Ran junk basket and gauge ring to 6350'. Set Model D packer @ 6330'. Ran Baker prod. tube seal assembly with on-off tool with plug in top of on-off tool on 2" tubing. Set seal assembly in Model D and pulled 2" tubing. Ran Baker retrievable BP and Baker full bore packer on 3-1/2" frac tubing. Set BP @ 6305". Spotted 3 sacks sand on BP. Treated with 5,000 gals. 15% NE acid and 70 ball sealers. Fraced w/30,000 gals. Poly-Vis and 45,000# of 20-40 sand, 1700# salt, and 800# benzoic acid flakes. Layed down 3-1/2" tubing and treating packer. Ran 2" tubing w/retrieving tool. Washed out sand and frac balls to top of BP. Recovered BP. Ran long string 2-1/16" tubing w/parallel anchor and top half of on-off tool. Latched unto on-off connector. Ran short string 2-1/16" tubing and latched into parallel anchor at 5904 . Pulled wire line plug in Drinkard tubing. Opened Tubb on 22/64" choke. Both zones flowing.

\$ IGNED	riginal Signed By C. L. WADE	TITLE Area Supt.	DATE 6-18-75
APPROVED BY	Orig. Signed 1.	TITLE	009 03 1975