Form C-103 State of New Mexico Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources Revised March 25, 1999 District 1 WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-025-06815 District II OIL CONSERVATION DIVISION 5. Indicate Type of Lease 811 South First, Artesia, NM 87210 2040 South Pacheco District III FEE 😠 STATE  $\square$ 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87505 District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: J. N. CARSON (NCT-A) Oil Well X Gas Well Other 8. Well No. 2. Name of Operator Chevron U.S.A. Inc. 9. Pool name or Wildcat 3. Address of Operator PADDOCK: P.O. Box 1150 Midland, TX 79702 4. Well Location 766 feet from the feet from the line and line Unit Letter Township 215 Range **NMPM** County LEA Section 28 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REMEDIAL WORK **ALTERING CASING** PERFORM REMEDIAL WORK PLUG AND ABANDON X **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. **PLUG AND ABANDONMENT** CASING TEST AND **MULTIPLE PULL OR ALTER CASING CEMENT JOB** COMPLETION OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. CHEVRON PROPOSES TO P&A PER ATTACHED PROCEDURE THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO HEARROYED. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE REGULATORY O.A. 8/9/01 DATE -SIGNATURE. Telephone No. (915)687-7148 Type or print name J. (This space for State use) APPROVED BY\_ \_\_ TITLE

-Conditions of approval, if any:

J. N. Carson (NCT-A) # 8 Paddock Field T21S, R37E, Section 28 Job: Plug And Abandon

## Procedure:

This well is located in or near a public area of the city of Eunice. Before commencing work, have a risk assessment performed by the FCS. If the work cannot be performed with the safety of the public assured, then perform this abandonment with a single derrick rig under supervision of the FCS.

- 1. MI & RU pulling unit. Bleed pressure from well, if any. Pump down csg with 8.7 PPG cut brine water, if necessary to kill well. Remove WH. Install BOP's and test to 1000 psi.
- 2. POH with 2 3/8" tubing string. LD tubing string and SN while POH.
- 3. PU 6 ¼" MT bit and GIH on 2 7/8" work string to approximately 5050'. POH with 2 7/8" work string and bit. LD bit.
- 4. MI & RU electric line unit. GIH and set CIBP at 5000'. POH. GIH and dump 35' cmt on top of CIBP at 5000'. POH. GIH and perforate from 2850-51' with 4 JSPF at 90 degree phasing. POH. RD and release electric line unit.
- 5. PU and GIH with 2 7/8" work string open-ended to 4950'. LD and tag top of cmt on CIBP at 4965' (CIBP set at 5000' with 35' cmt on top). Displace casing with 9.5 PPG salt gel mud from 4965'. POH with 2 7/8" work string.
- 6. PU and GIH with 7" pkr on 2 7/8" work string to 2750'. Set pkr at 2750'. Establish pump-in rate into squeeze holes at 2850-51' using fresh water. Open 13 3/8" surface casing valve and 9 5/8" intermediate csg valve while pumping and observe for circulation to surface. If circulation is obtained, circulate fresh water to surface at maximum pump rate until returns are clean. POH with 2 7/8" work string and pkr. LD pkr. Note: If cannot pump into perfs 2850-51, contact Gary Wink at NMOCD to obtain permission for balanced cement plug from 2900-1100' inside 7" csg.
- 7. PU and GIH with tbg-set CICR on 2 7/8" work string to 2750'. Set CICR at 2750'. Pressure test csg and CICR to 300 psi. Establish pump-in rate into perfs 2850-51'. Hold 300 psi on tbg/csg annulus during sqz job.
- 8. RU cementing equipment. Cement squeeze perfs 2850-51' using Class C cement mixed to 14.8 PPG w/ 1.32 CFY. Circulate cement to surface through 9 5/8" intermediate casing and then close 9 5/8" intermediate csg valve. After closing intermediate casing valve,

- attempt to achieve 1500 psi squeeze pressure. Note: Perform entire squeeze job with 13 3/8" surface casing valve open. If cement circulates to surface through 13 3/8" surface casing, close surface casing valve and continue job.
- 9. Sting out of cement retainer. Reverse circulate clean from 2750' using 9.5 PPG salt gel mud. PUH to 2450'. Spot balanced cmt plug from 2350-2450'. PUH to 1300'. Reverse circulate well clean from 1300' using 9.5 PPG salt gel mud. WOC 2 hrs. LD and tag cmt plug at 2350'. PUH and spot balanced cmt plug from 1100-1300'. PUH to 800'. Reverse circulate well clean from 800' using 9.5 PPG salt gel mud. WOC 2 hrs. LD and tag cmt plug at 1100'. POH with 2 7/8" work string.
- 10. MI & RU electric line unit. GIH and perforate from 250-54', 298-302', and 350-54' with 4 JSPF at 90 degree phasing. POH. RD and release electric line unit.
- 11. PU and GIH with 7" pkr on 2 7/8" work string to 230'. Set pkr at 230'. Establish pumpin rate into perfs 250-354'. Open 13 3/8" surface casing valve and 9 5/8" intermediate csg valve while pumping and attempt to establish circulation to surface. Circulate fresh water to surface at maximum pump rate until returns are clean. POH with 2 7/8" work string and pkr. LD pkr.
- 12. PU and GIH with tbg-set CICR on 2 7/8" work string to 230'. Set CICR at 230'. Pressure test csg and CICR to 300 psi. Establish pump-in rate into perfs 250-354'. Hold 300 psi on tbg/csg annulus during sqz job.
- 13. RU cementing equipment. Cement squeeze perfs 250-354' using Class C cement mixed to 14.8 PPG w/ 1.32 CFY. Circulate cement to surface through 13 3/8" surface casing and then close 13 3/8" surface csg valve. After closing surface casing valve, attempt to achieve 1500 psi squeeze pressure. Note: Perform entire squeeze job with 9 5/8" intermediate casing valve open. After achieving final squeeze pressure, close 9 5/8" intermediate casing valve to prevent gas migration.
- 14. Sting out of cement retainer. Reverse circulate clean from 225' using fresh water. POH with work string and stinger. LD stinger. SWI overnight for cement to cure.
- 15. Open well. Check for gas flow from 13 3/8" surface casing and from 9 5/8" intermediate casing. Note: If gas flow is detected, contact Engineering for additional procedures before proceeding. GIH w/ 2 7/8" open-ended work string to 230'. Tag CICR at 230'. Displace fresh water from csg using 9.5 PPG salt gel mud. PUH and spot Class "C" cement plug inside casing from 60' to surface. RD cementing equipment.
- 16. Remove BOP's. RD and release pulling unit.
- 17. Cut off all casings 3' below ground level. Weld steel plate with 1/2" valve (plugged with 1/2" FS plug) on top of casing strings. Backfill and install NMOCD P&A marker.

18. Clear and bioremediate well location.

AMH 8/8/2001

Ely: A. M. Howell

Updated: 8/8/2001

