

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-39

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-06839

5. Indicate Type of Lease

STATE ☐

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

Chevron U.S.A. Inc.

3. Address of Operator

P.O. Box 670, Hobbs, NM 88240

4. Well Location

Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line

Section 28

Township 21S

Range 37E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☒

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed: 2-11-89 thru 2-18-89

POOH w/rods and pump. Establish circulation with foam. Cleanout to 3788. Circulate clean. Set pkr at 3536. Acidize open hole 3598-3788 w/1000 gallons 15% NEFE HCL. Swab. Install tree saver and pop off valve. Frac open hole w/20,000 gallons + 35,500# 20/40 Ottawa sand. RD tree saver and frac equip. Swab. Break circulation w/foam mist. Wash out fill from 3753' to 3788'. Circulate hole clean. TIH w/ tbg testers, tst to 4000psi Run 2 3/8" production tbg to 3747'. Perf sub at 3711-15, SN at 3710'. Run rods and pump. Load tbg w/17bbbls 9#BW. Pressure to 500psi, ok. Check pump action, ok. Cleanout location, release rig 2-18-89.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. K. Emore

TITLE Technical Assistant

DATE 2-17-89

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 8 1989