

Cont. From Page 1

9. GIH w/retrieving head, RDG pkr - & SN on 2-3/8" tbg. Swab test squeeze.
10. Reset BP @ 5400. Test csg to 1000#.
11. POH w/pkr & BP.
12. GIH w/overshot and retrieve DR plug @ 5762 and POH.
13. GIH w/4-3/4" bit on 2-3/8" tbg. Drill Mod "D" pkr and push to below 6300'.
14. POH w/bit.
15. GOI perf Blinebry & Tubb formations w/3-1/8" select fire csg gun. Perf from Welox GR-Neutron log dated 3/22/61 @: Blinebry 5598, 5605, 81,84,89,5757,65, 71,5805,08,12,14,40,46; Tubb 6077, 80,83,89,6111,14,17,20,23,26,29,32,37,39,41, 46,49,52,55,58,61,64,67,70,73,79,82,85,88,& 91. Total 44 shots. -
16. GIH w/Watson RBP, Baker RDG pkr & SN on 2-3/8" tbg. Set BP @ 6220' & pkr @ 6210 Test BP to 2000#.
17. a). Halliburton spot 100 gal 15% HCl 6191-6077. Reset pkr @ 6020. Break down perfs. Open bypass & displ acid to pkr, close bypass, acidize Tubb perfs 6077-6191 w/3000 gal 15% HCl in 6 equal stages. Drop 8 RCNB's after each of the first 5 stages (total 40 Balls). Displace w/27 bbl 2.0% KCl water. Rate 3 BPM.
b). Set BP @ 5940. Set pkr @ 5930 & test BP to 2000#. Reset pkr @ 5865. Open bypass & displace acid to pkr, close bypass. Acidize Blinebry perfs 5874-5910 w/1500 gal 15% HCl in 3 equal stages. Drop 15 RCNB after 500 & 1000 gal acid. (Total 30 balls). Displ w/24 bbl 2.0% KCl water. Rate 3 PBM.
c). Set BP @ 5865 & pkr @ 5855. Test BP to 2000#. Reset pkr @ 5715. Open bypass & displ acid to pkr, close bypass. Acidize Blinebry perfs 5728-5846 w/1500 gal 15% HCl in 3 equal stages. Drop 12 RCNB's after 500 & 1000 gal. (total 24 balls). Displ w/25 bbl 2.0% KCl water. Rate 3 BPM.
d). Set BP @ 5720 & pkr @ 5710. Test BP to 2000#. Reset pkr @ 5520. Open bypass, displace acid to pkr & close bypass. Acidize Blinebry perfs 5536-5700 w/1200 gal in 3 equal stages. Drop 9 RCNB's after 400 & 800 gal. (total 18 balls). Displ w/26 bbl 2.0% KCl water. Rate 3 BPM.

All acid and flush is to contain 2 gal Pen-5/1000 gal. Acid is to also contain 1 gal Superflo & 1 gal Matriseal -0-/1000 gal.
18. POH w/pkr & BP. Lay down tbg.
19. GIH w/Baker Loc-set pkr on 2-1/16" OD. 1 J. (lower) tbg. Set pkr @ 6050+ w/pkr in neutral. Run 2-1/16" OD. 1 J (upper) tbg w/1.9" SN on bottom. Set SN @ 5915+.
20. Remove BOP. Nipple up tree.
21. Swab in both zones.
22. RD & RR.