

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

## NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator <b>Sunray DX Oil Company</b> 3. Address of Operator <b>P. O. Box 1416, Roswell, New Mexico</b> 4. Location of Well UNIT LETTER <b>H</b> <b>2310</b> FEET FROM THE <b>N</b> LINE AND <b>330</b> FEET FROM THE <b>E</b> LINE, SECTION <b>29</b> TOWNSHIP <b>21S</b> RANGE <b>37E</b> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) <b>3472 GR</b>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> 5. State Oil & Gas Lease No. 7. Unit Agreement Name 8. Farm or Lease Name <b>D. Hardy</b> 9. Well No. <b>3</b> 10. Field and Pool, or Wildcat <b>Blinbry Gas</b> 12. County <b>Lea</b>
---	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> <b>Perf add'l section &amp; frac</b>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Run tbg and insert Baker DR plug in Mod D pkr at 5862'. Dump 6' - 8' sd on plug.
2. Run "E" gun and perf 5533-34 w/4 shots for block squeeze.
3. Block squeeze to 6000 psig w/100 ax batches of Incon Poz. WOC 8 hrs & drill out. Pressure test squeeze to 3000 psig.
4. Perforate selected intervals within Blinbry Gas zone (5536-5828).
5. Run tbg w/Retrievable Bridge Plug and Retrievmatic Pkr and acidize perfs w/2200 gal BDA.
6. Swab test. If required, frac w/30,000 gal refined oil & 60,000 lb sd.
7. Swab, establish flow, recover all load oil and take production test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **B.F. Brawley** TITLE **District Engineer** DATE **2-14-66**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: