

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

H. T. Mattern NCT-B

8. Well No.

5

9. Pool name or Wildcat
Penrose Skelly - Eumont

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Chevron U.S.A. Inc.

3. Address of Operator

P.O. Box 670, Hobbs, NM 88240

4. Well Location

Unit Letter 0 : 810 Feet From The South Line and 1980 Feet From The East Line

Section 30

Township 21S

Range 37E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: sqz, acidz, frac Abandon Eumont ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed: 2-17-89 thru 3-3-89

POH w/production equip. NU BOP and test WH to 500psi, ok. Set pkr at 3512'. Isolate perfs 3530-3618-, brkdn at 1000psi - ok. Set RBP at 3481 and pkr at 3386'. Isolate perfs (3408-3440). Establish injection rate 1 1/2 bpm at 1000psi. (10bbl). Set pkr at 3137' and RBP at 3386. (isolate 3158-3362) Set CICR at 3481', test tbg 1500psi, ok. Establish inj. rate at 1 bpm. Batch mix cmt, lead 150sx Cl C. tail w/ 50sx Cl C. Sting out, circ 50 sx to pit. PU CICR. Rev 32 sx to pit. WOC 24 hrs. Drlg cmt, cmt ret, to 3565. Wash to 3650'. TIH mill on pkr. Drlg on btm of pkr and scale 3656-3673. Circulate clean. Acidz open hole w/1000 gallons 15% NEFE acid. Swab. Frac OH w/20,000 gallons + 35,500# 20/40 ottowa sand. Swab back frac. TIH and c/o sand to 3800'. Circ clean. Run 2 3/4" SN at 3745. Run rods and pump. Space out, hang on, turn over to prod. 3-3-89.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. X. Elmore TITLE Technical Asst. DATE 3-8-89

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAR 10 1989

2 A Eumont, F

1161 1161

RECEIVED
MAR 9 1989
OCD
HOBBS OFFICE

RECEIVED
MAR 9 1989
OCD
HOBBS OFFICE