

L CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name V. M. Henderson
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 8
4. Location of Well UNIT LETTER <u>E</u> <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>North</u> LINE, SECTION <u>30</u> TOWNSHIP <u>21-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat Drinkard, Paddock & Penrose Skelly
15. Elevation (Show whether DF, RT, GR, etc.) 3510' (DF)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Install BOP.
2. Spot 40' Cement on top of CIBP from 3525' to 3485' in Penrose Skelly string.
3. Cut Penrose Skelly 2 3/8" casing @ 2550' and pull.
4. Set CIBP in Paddock String @ 3350' and spot 40' cement on top of plug from 3350'-3310'.
5. Cut 2 3/8" Paddock String casing @ 2500' and pull.
6. Set CIBP in Drinkard String @ 5100' and spot 40' cement on top of plug from 5100'-5060'.
7. Set CIBP in Drinkard String @ 3350' and spot 40' cement on top of plug from 3350'-3310'.
8. Cut 2 3/8" Drinkard tubing @ 2550' and pull.
9. Perforate 8 5/8" casing W/2-JS @ 1370' and 1300'.
10. Set cement retainer @ 1200'. Cement perms 1300'-1370'. to surface W600 sx. Class H Cement containing 2% CACL.
11. Leave cement retainer in hole and spot 1 bbl cement on top of plug.
12. Spot 35 sx cement plug from 380'-280'.
13. Spot 15 sx cement plug @ surface.
14. Install dry hole marker and clean location.
15. Well plugged and abandoned 12-28-83.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Mgr. DATE 1-5-84

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE AUG 7 1986

CONDITIONS OF APPROVAL, IF ANY: