
Office	Energy, Minerals and	d Natural Descurses		rorm '	
District I	Lindigy, williciais all	a radulal izezoulces	WELL API	Revised March 2	
16.35 N. French Dr., Hobbs, NM 87240 District II	OIL CONSEDU	A TION DIVICION	F	0-025-06972	
811 South First, Artesia, NM 87210		OIL CONSERVATION DIVISION 2040 South Pacheco		5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410		NM 87505	STAT	· ·	
District IV 2040 South Pacheco, Santa Fe, NM 8750	Sunta 1 0,	1111 01505		& Gas Lease No.	
(DO NOT USE THIS FORM FOR PRODIFFERENT RESERVOIR. USE "APPROPOSALS.)		EPEN OR PLUG BACK TO A	7. Lease Na	me or Unit Agreement Nar	
1. Type of Well: Oi Well 🗷 Gas Well	Other		J. N. CARS	ON (NCT-C)	
2. Name of Operator		- · · · · · · · · · · · · · · · · · · ·	8. Well No.		
Chevron U.S.A. Inc.			5		
3. Address of Operator	50500			e or Wildcat	
P.O. Box 1150 Midland, TX 4. Well Location	79702		PADDOCK		
	010 7 7		000		
Unit Letter A :	_	NORTH line and		eet from the EAST	
Section 33		Range 37E	NMPM	County LE	
	10. Elevation (Show w	hether DR, RKB, RT, GR, e	etc.)		
11. Checl	k Appropriate Box to In	dicate Nature of Notice	Report. or 0	Other Data	
	NTENTION TO:		-	REPORT OF:	
PERFORM REMEDIAL WORK		•		☐ ALTERING CASI	
EMPCRARILY ABANDON [CHANGE PLANS	COMMENCE DRIL	LING OPNS.	PLUG AND ABANDONMENT	
PULL CR ALTER CASING [MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB)	ADANDONNIENT	
OTHER:		OTHER:			
of starting any proposed work or recompilation. CHEVRON PROPOSES TO CON	NTINUE P&A PER ATTACHED		Č		
			·		
		HOURS PLA	DR TO THE DPERATIONS	SE NOTIFIED 28 FORMING OF FOR THE CAGG	
hereby certify that the information ab	ove is true and complete to the	HOURS PAR PLUGORNO (TO SE ARM	DR TO THE OPERATIONS (OMED)	BE NOTIFIED 34 FOREINING OF	
hereby certify that the information ab	ove is true and complete to the	HOURS PAR PLUGORNO (TO SE ARM	DR TO THE OPERATIONS COVED.	BE NOTIFIED 34 FOREINING OF	
IGNATURE G.K. RY	sley	HOURS PARE PURGOING OF SELECTION OF MY knowledge and beli	DR TO THE OPERATIONS ROVED.	BE NOTIFIED 28 FOR THE CAG3 DATE 8/3/01	
IGNATURE J. K. RIPLES	sley	HOURS PARE PURGOING OF SELECTION OF MY knowledge and beli	DR TO THE OPERATIONS ROVED.	BE NOTIFIED OF THE CAGO	
OV Di	sley	HOURS PARE PURGOING OF SELECTION OF MY knowledge and beli	DR TO THE OPERATIONS ROVED.	BE NOTIFIED 28 FOR THE CAG3 DATE 8/3/01	



J. N. Carson (NCT-C) # 5 Paddock Field T21S, R37E, Section 33 Job: Plug And Abandon

Procedure # 2: (Drill Out Surface Plug And Cmt Sqz)

This well is located in or near a public area of the city of Eunice. Before commencing work, have a risk assessment performed by the FCS. If the work cannot be performed with the safety of the public assured, then perform this abandonment with a single derrick rig under supervision of the FCS.

- 1. PU and GIH with 6 ¼" MT bit and DC's on 2 7/8" work string. Establish reverse circulation using fresh water. LD and drill out cement inside 7" csg from surface to approximately 400'. Reverse circulate well clean from 400' using fresh water. POH with 2 7/8" work string. LD bit and DC's.
- 2. MI & RU electric line unit. GIH and perforate from 240-44', 288-92', and 350-54' with 4 JSPF at 90 degree phasing. POH. RD and release electric line unit.
- 3. PU and GIH with 7" pkr on 2 7/8" work string to 220'. Set pkr at 220'. Establish pumpin rate into perfs 240-354'. Open 13 3/8" surface casing valve and 9 5/8" intermediate csg valve while pumping and attempt to establish circulation to surface. Circulate fresh water to surface at maximum pump rate until returns are clean. POH with 2 7/8" work string and pkr. LD pkr.
- 4. PU and GIH with tbg-set CICR on 2 7/8" work string to 220'. Set CICR at 220'. Pressure test csg and CICR to 300 psi. Establish pump-in rate into perfs 240-354'. Hold 300 psi on tbg/csg annulus during sqz job.
- 5. RU cementing equipment. Cement squeeze perfs 240-354' using Class C cement mixed to 14.8 PPG w/ 1.32 CFY. Circulate cement to surface through 13 3/8" surface casing and then close 13 3/8" surface csg valve. After closing surface casing valve, attempt to achieve 1500 psi squeeze pressure. Note: Perform entire squeeze job with 9 5/8" intermediate casing valve open. After achieving final squeeze pressure, close 9 5/8" intermediate casing valve to prevent gas migration.
- 6. Sting out of cement retainer. Reverse circulate clean from 215' using fresh water. POH with work string and stinger. LD stinger. SWI overnight for cement to cure.
- 7. Open well. Check for gas flow from 13 3/8" surface casing and from 9 5/8" intermediate casing. Note: If gas flow is detected, contact Engineering for additional procedures before proceeding. GIH w/ 2 7/8" open-ended work string to 220'. Tag CICR at 220'.

Displace fresh water from csg using 9.5 PPG salt gel mud. PUH and spot Class "C" cement plug inside casing from 60' to surface. RD cementing equipment.

- **8.** Remove BOP's. RD and release pulling unit.
- 9. Cut off all casings 3' below ground level. Weld steel plate with 1/2" valve (plugged with 1/2" FS plug) on top of casing strings. Backfill and install NMOCD P&A marker.
- 10. Clear and bioremediate well location.

AMH 8/3/2001