

Submit 3 Copies
to Appropriate
District Office

2

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer Dd, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)	30-025-06993
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	N/A
7. Lease Name or Unit Agreement Name	CENTRAL DRINKARD UNIT
8. Well No.	156
9. Pool name or Wildcat	DRINKARD
10. Elevation(Show whether DF, RKB, RT, GR, etc.)	3456' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
CHEVRON U.S.A. INC.

3. Address of Operator
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE

4. Well Location
Unit Letter 0 : 589 Feet From The SOUTH Line and 1909 Feet From The EAST Line
Section 33 Township 21S Range 37E NMPM LEA County

11 Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	<input type="checkbox"/>	REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	COMMENCE DRILLING OPNS.	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	CASING TEST AND CMT JOB	<input type="checkbox"/>
OTHER:	<input type="checkbox"/>	OTHER:	<input type="checkbox"/>
PLUG AND ABANDON	<input type="checkbox"/>	ALTER CASING	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>	PLUG AND ABAN.	<input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.

WORK PERFORMED 1-7 THRU 1-11-94
PLUG #1, SET CIBP @ 6500', W/25 SX CMT ON TOP. (COVERS 5-1/2" SHOE)
PLUG #2, 35 SX CMT F/4900-5320' (COVERS GLORIETTA)
PLUG #3, PERF 5-1/2" CSG @ 3850, SQZ W/50 SX CMT. (COVERS 8-5/8" SHOE)
PLUG #4, PERF @ 250', SQZ W/65 SX PLUG 1150-1300' (COVERS SALT ZONE)
CIRCULATE TO SURFACE.
PLUG #5, PERF @ 250', SQZ 100 SX PLUG 350-SURFACE (COVERS 13-3/8" SHOE)
PLACE 9.5 PPG MUD BETWEEN ALL PLUGS.
PULL DEAD MAN ANCHORS, FILL PITS, LEVEL LOCATION, PLACE P&A MARKER
CHANGE STATUS OF WELL TO PLUGGED AND ABANDONED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Nita Rice TITLE TECHNICAL ASSISTANT DATE: 1/12/94

TYPE OR PRINT NAME NITA RICE TELEPHONE NO. (915)687-7436

APPROVED BY Charles... TITLE DIRECTOR DATE FEB 15 1994
CONDITIONS OF APPROVAL, IF ANY:

Scanned