NO. OF COPIES RECEIVED	<b>]</b> .			Form C-103 Supersedes Old		
DISTRIBUTION SANTA FE	NEW MEXICO	OIL CONSERV	TION COMMISSION	C-102 and C-10 Effective 1-1-6		
FILE	1			5a. Indicate Type	of Legae	
U.S.G.S.	_			State	Fee X	
LAND OFFICE	_			5. State Oil & Gas	the second s	
OPERATOR			•			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)					7. Unit Agreement Name	
1. OIL CAS CAS WELL	OTHER-		·	8. Farm or Lease		
2. Name of Operator Mobil Oil Corporation					Marshall Comm.	
3. Address of Operator Three Greenway Plaza East, Suite 800, Houston, Texas 77046					L or Wildow	
4. Location of Well F	1980	North	1980	10. Field and Poor Eunice Dr		
West	PEET FROM THE 34	215	37E			
		Show whether DF, 3443 GR	RT, GR, etc.)	12. County Lea		
	k Appropriate Box To INTENTION TO:	Indicate Natu	re of Notice, Report o SUBSEQ	r Other Data UENT REPORT OF:		
Notice of			r-	۰		
PERFORM REMEDIAL WORK	PLUG AND		MEDIAL WORK	1	AND ABANDONMENT	
TEMPORARILY ABANDON	CHANGE P		SING TEST AND CEMENT JOB			
PULL OR ALTER CASING			OTHER		[_]	
OTHER						
17, Describe Proposed or Completed	Operations (Clearly state a	ll pertinent details,	and give pertinent dates, inc	luding estimated date of	starting any proposed	
work) SEE RULE 1103.					-	
1. Hot oil tbg w/25	5 bbls lease oil					
2. Kill well w/free	sh water containir	ag 2% KCl an	d circulate out o	il.		
3. Pull 2 3/8" tbg						
4. Set retrievable and dump 5 sx sa	bridge plug @ 640 and on BP).	)0' <u>+</u> and lo	ad hole w/2% KCl	water. (Set RH	SP on wireline	
5. Pressure up on 5" Prod. csg and check for leaks. Repair and/or squeeze if necessary.						
6. Perf 5" csg @ 1450'+ w/4 shots, (calculated cmt top @ 1600').						
7. Determine pumpin of 1000 psig, a	ng rate into perf: cidize w/500 gal.	s @ 1450'. 15% HC1 + 3	If pumping test i 15 Bbls water for	ndicates press breakdown.	ire in excess	
"C" cmt, (150 s into formation	r on 2 7/8" work a x for fill-up of or holes in 7" cs	7" x 5" ann g.)	(over)	fs @ 1450' w/2 sqz of possibl	50 sx Class e bleed-off	
18. I hereby certify that the inform	nation above is true and comp	lete to the best of	my knowledge and belief.			
J. W. Du			horized Agent	DATE	/20/78	
	geig. Sie			CATE -	67 13/b	
APPROVED BY	John	TITLE				

17. (9. continued)

9. W.O.C.

10. Establish a pumping rate down the 9 5/8" x 7" csg annulus and if necessary treat down the annulus as in step 7.

Bradenhead sqz the 9 5/8" x 7" annulus w/350 sx Class "C" cmt, (200 sx for annular volume 11. of 9 5/8" x 7 " + 150 sx for sqz into formation and/or holes in csg).

W.O.C., then drill out retainer and cmt in 5" csg and test sqz job. 12.

13. Pull RBP @ 6400'.

14. Run a treating pkr on 2 7/8" work string and set @ 6400'+. Test Tbg in hole to 6500#. Load back side and pressure up 500 to 1000#.

15. Frac the drinkard perfs 6464'-6608' w/3000 gal. 15% HC1 + 30,000 gal. gelled fresh water + 37,500# 20/40 saud in 3 stages. Treat @ maximum rate, not to exceed 30 BPM or 6000# TTP.

Stages 1 & 2:

- (a) Pump 1000 gal. 15% Acid
- (b) Pump a 2,000 gal. gelled water pad
- (c) Pump 2,000 gal. gelled water + 1#/gal. 20/40 sand
- (d) Pump 3,000 gal. gelled water +  $1\frac{1}{2}$  #/gal. 20/40 sand
- (e) Pump 3,000 gal. gelled water + 2#/gal 20/40 sand

(f) Pump 250# rock salt + 100# Bezoic Acid flakes in 400 gal. gelled brine.

Stage 3:

(a) Repeat steps (a) through (e) of stage 2

(b) Flush to perfs and overflush w/50 bbls treated 2% KCl water.

16. Pull 2 7/8" work string & packer, run 2 3/8" prod. tbg. and swab back as necessary.

NAR 2 4 1978

OIL CONSERVATION COMM. HOBBS, N. M.