

ATTACHMENT - (DETAIL SHEET)

1. Rig up, kill well & pull tbg.
2. Run GR-Neutron Log & set trt pkr at 6470' on 2 1/2" tbg.
3. Squeeze old Drk. perms with frac sand & clean out to 6480'.
4. Pull tbg & pkr & set CIBP on Wire Line at 6475'.
5. Reperforate Drinkard approx. 6455-58' w/1 JSPP & treat w/1000 gal 15% LSTNE acid; then frac w/10,000 gal. crude, 10,000 lbs. sand & 500 lbs. "ADOMITE" ADDITIVES.
6. Swab load & test.
7. Set Model "D" pkr. at 6400' & perf Blinebry approx. 5715-22', 5782-84, 5793-95, 5801-03, 5810-12, & 5825-32' w/1 JSPP.
8. Trt. Blinebry w/2000 gals. acid and frac w/20,000 gals. crude, 20,000 lbs. sand & 1000 lbs. "ADOMITE" ADDITIVES.
9. Swab & test.
10. Run dual strings of 2 1/16" tubing and place on production.

Administrative Information

1. Project Title : [Project Title]
2. Project Number : [Project Number]
3. Project Location : [Project Location]
4. Project Start Date : [Project Start Date]
5. Project End Date : [Project End Date]
6. Project Manager : [Project Manager]
7. Project Sponsor : [Project Sponsor]
8. Project Budget : [Project Budget]
9. Project Status : [Project Status]
10. Project Description : [Project Description]