Submit 3 Copies to Appropriate	State of New Me Energy, Minerals and Natural F		Form C-103 Revised 1-1-89
District Office DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980 DISTRICT II P.O. Drawer DD, Artesia, NM 88210	OIL CONSERVATIO 2040 Pacheco Santa Fe, NM	St.	WELL API NO. 30-025-03037 5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PR DIFFERENT RESE	ICES AND REPORTS ON WEL OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PEF -101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Mark Owen
2. Name of Operator Marathon 011 Company 3. Address of Operator P.0. Box 2409 Hobbs. NM 8			8. Well No. 1 9. Pool name or Wildcat 14.bb
4. Well Location Unit Letter :198	0 Feet From The South	Line and 198	30 Feet From The East Line
Section 35	10. Elevation (Show wheth		
•	ppropriate Box to Indicate NTENTION TO:	1	Report, or Other Data SEQUENT REPORT OF:
		REMEDIAL WORK	
TEMPORARILY ABANDON		COMMENCE DRILLING	
OTHER:		OTHER:	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Marathon Oil Compnay plans on cement squeeze the old Paddock perfs and install smaller tubing for the Tubb gas production using the attached procedure.

SIGNATURE Thomas I Kaset	TITLE Production Engineer	DATE	5-08-98
TYPE OR PRINT NAME Thomas P. Kacir		TELEPHONE NO.	505-393-710
(This space for State Use)			
OPIGINAL SIGNED BY	TITLE	DATE	19 1998

3



,

•

Mark Owen Well No. 1 UL L, 1980' FSL and 660' FEL Section 35, T-21-S, R-37-E Lea County, New Mexico

Purpose: Squeeze Paddock Perfs and Install 2 3/8" Tubing for Tubb

PROCEDURE

- 1. MIRU PU. Kill well as necessary with 2% KCl water. ND wellhead and NU BOP equipment.
- 2. Release Baker Lok-Set packer at 5864'. TOOH.
- 3. RIH with conventional sand pump on sand line. Clean fill out to PBTD at 6295'.
- 4. TIH with packer and CIBP. Set CIBP at 5300'.
- 5. PU and set packer at 5250'. Test CIBP to 1000 psi. Release packer and PUH.
- 6. Set packer at 5125'. Test old squeezed perfs from 5142'-5212' to 500 psi.
- 7. Release packer and POOH.
- 8. TIH with 5 ½" cement retainer, stinger and seating nipple on 2-7/8" tubing.
- 9. Set retainer at 4950'. RU Halliburton.
- 10. Sting into retainer. Pressure up backside to 700 psi. Test tubing to 3000 psi.
- Establish injection rate. Mix and pump cement. Wash up pump and lines. If after total displacement, no positive pressure is observed, over flush retainer and prepare to resqueeze.
- 12. If good squeeze occurs with pressure and full displacement has not occurred, sting out of retainer and reverse cement to pit.
- 13. RD Halliburton. POOH with stinger.
- 14. TIH with 4-3/4" bit and Drill Collars on 2 7/8" tubing to top of retainer.
- 15. RU drilling head and power swivel. Drill out retainer and cement to top of CIBP. PU and test squeezed interval to 500 psi.
- 16. If squeeze holds, then drill out CIBP. POOH, laying down drill collars and 2 7/8" tubing.
- 17. RIH with conventional sand pump on sand line. Clean fill out to PBTD at 6295'.
- 18. TIH (from bottom to top) with 1 joint of 2 3/8" tubing, API SN and 2 3/8" tubing to surface. Land tubing at 6070'.
- 19. ND BOP equipment. NU wellhead. RU swab. Swab well in. RDMO PU.
- 20. Connect surface equipment and start well pumping to production facilities. Monitor production and producing fluid level.

