Submit 3 Copies to Appropriate E	State of New M nergy, Minerals and Natura	l Resources Department	Form C-103 Revised 1-1-89
District Office	IL CONSERVATI	ON DIVISION	
P.O. Box 1980, Hobbs NM 88240	P.O. Box		WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mex	ico 87504-2088	<u>30-025-07039</u> 5. Indicate Type of Lease
DISTRICT III			
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOTICE	ES AND REPORTS ON WI	ELLS	
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPE DIR. USE "APPLICATION FOR P		7. Lease Name or Unit Agreement Name
(FORM C-10	1) FOR SUCH PROPOSALS.)		MARK OWEN
I. Type of Well: OIL GAS GAS			
	OTHER		
2. Name of Operator Marathon Oil Company			8. Well No.
3. Address of Operator		··· ··· ··· ··· ··· ··· ··· ··· ··· ··	 Pool name or Wildcat
P.O. Box 552, Midland, TX	79702		BLINEBRY OIL & GAS
Unit Letter N : 660	Feet From The SOUT	H Line and 19	80 Feet From The WEST
			80 Feet From The WEST Li
Section 35	Township 21-S	Range 37-E	NMPM LEA Count
		ther DF, RKB, RT, GR, etc L:3356 KB:3378)
			Report, or Other Data
			SEQUENT REPORT OF:
NOTICE OF INT			SEQUENT REFUNITOR:
	_		
		REMEDIAL WORK	
	PLUG AND ABANDON		
	 	REMEDIAL WORK	
ERFORM REMEDIAL WORK	 	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEI	OPNS. PLUG AND ABANDONMENT
RFORM REMEDIAL WORK	CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEI OTHER: <u>RECOMPLE</u> etails, and give pertident date	OPNS. PLUG AND ABANDONMENT MENT JOB
RFORM REMEDIAL WORK	CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEL OTHER: <u>RECOMPLE</u> etails, and give pertinent date . Tested BOP. S Blinebry 5812-18 Pkr and RBP, Act 00 gallons 70% CC up. POOH with S 5 2 3/8" tubing. g tbg annulus wit led Tbg plug. Sw owing. RDMO PU.	OPNS. PLUG AND ABANDONMENT MENT JOB TE TO BLINEBRY OIL & GAS Set CIBP @ 6337. Dumped 5 sack 5, 5794-98, 5728-34, 5658-61, icized 5386-5818 with 2500 D2 foam carrying 214,000# 16/3 Stimulation string. RIH with Set Pkr @ 5324'. Set plug i th 120 barrels chemically wabbed well to frac tank to RU Coiled TBG RIH with CT
In the second s	CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEI OTHER: <u>RECOMPLE</u> etails, and give pertinent date . Tested BOP. S Blinebry 5812-18 Pkr and RBP, Act 00 gallons 70% CC up. POOH with S 5 2 3/8" tubing. g tbg annulus wit led Tbg plug. Sw owing. RDMO PU. T. Turned into s	OPNS. PLUG AND ABANDONMENT MENT JOB TE TO BLINEBRY OIL & GAS TE TO BLINEBRY OIL & GAS TE TO BLINEBRY OIL & GAS State of the starting any propose Set CIBP @ 6337. Dumped 5 sack 5, 5794-98, 5728-34, 5658-61, icized 5386-5818 with 2500 D2 foam carrying 214,000# 16/3 Stimulation string. RIH with 2500 D2 foam carrying 214,000# 16/3 Stimulation string. RIH with Set Pkr @ 5324'. Set plug in the 120 barrels chemically wabbed well to frac tank to RU Coiled TBG. RIH with CT Sales line. 2/25/95
Image: Signature Image: Signature Image: Signature Image: Signature	CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEI OTHER: <u>RECOMPLE</u> etails, and give pertinent date . Tested BOP. S Blinebry 5812-18 Pkr and RBP, Act 00 gallons 70% CC up. POOH with S 5 2 3/8" tubing. g tbg annulus wit led Tbg plug. Sw owing. RDMO PU. T. Turned into s	OPNS. PLUG AND ABANDONMENT MENT JOB

- *



ALA DE 1035 CEFFICE

.