

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION  
10885 OFFICE D. C. C.

JUL 28 11 45 AM '67

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Mobil Oil Corporation	8. Farm or Lease Name New Mexico "F"
3. Address of Operator P. O. Box 633, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>20S</u> RANGE <u>38E</u> NMPM.	10. Field and Pool, or Wildcat Terry Blinbry
15. Elevation (Show whether DF, RT, GR, etc.) 3563	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER Plug Back & Recomplete <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU pulling unit and pull rods & tubing.
2. Run 5 1/2" 17# gage ring on wire line to 5450'. Set 5 1/2" 17# CIBP at 5450' & cap w/20' Hydromite.
3. Perforate San Andres 1 JSPI from Lane Wells G.R.-N log dated 2-16-55 at 4592, 94, 96, 98, 4600, 03, 05, 07, 09, 11, 4778, 79, 80, 91, 93, 5217, 19, 21, 23, 25, 29, 33, 34, 5301, 03, 05, 07, 11, 13, 15 - Total of 30 holes.
4. Go in hole w/RBP & treating; pkr and isolate lower set perms from 5217-5315.
5. Acidize perms from 5217 to 5315 (15 holes) w/1000 gals of 15% NE HCL acid using ball sealers to ball off perms. Swab acid wtr back & test. Squeeze perms if necessary. Run after acid log to evaluate acid job.
6. Move RBP and packer to isolate upper perms from 4592-4793 (15 holes) repeat step 5.

(continued on attached sheet)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>John J. Thurd</u>	TITLE <u>Authorized Agent</u>	DATE <u>7-27-67</u>
APPROVED BY <u>[Signature]</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		