

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease
State ☐ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Sun Exploration and Production Company 3. Address of Operator P. O. Box 1861, Midland, Texas 79702 4. Location of well UNIT LETTER L 1980 3050 FEET FROM THE South LINE AND 760 FEET FROM THE West LINE, SECTION 9 TOWNSHIP 22-S RANGE 36-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 12. County Lea	7. Unit Agreement Name 8. Farm or Lease Name State "A" A/C2 9. Well No. 32 10. Field and Pool, or Wildcat South Eunice 7 Rvrs Queen
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Use backhoe to dig out around P&A marker to locate point where csg. cut off. Build cellar. Remove P&A marker. Weld on 5½" nipple to surface. Install well-head.
- MIRU well service unit. Drill out cmt in 5½" csg.
- Lower 4-3/4" bit & DC's.
- Circ. hole w/9 PPG mud laden fluid. POH w/bit & DC's.
- Use csg cutters to cut 5½" csg at 1200'. POH w/csg.
- RIH w/2-7/8" WS. Spot 100' cmt plug from 1250-1150. (50' in csg stub and 50' out). POH.
- Perforate 8-5/8 csg at 1000' using 4 way perforator. RIH w/FB pkr on WS. Set pkr at 950. Attempt to establish circ to surface. If unable to do so, POH w/WS & pkr. Re-perf 100' higher and attempt to establish circ.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dee Ann Kemp TITLE Associate Acct DATE 8-3-84
ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT 1 SUPERVISOR TITLE DATE AUG - 7 1984
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG - 6 1984

O.C.D.
HOBBS OFFICE

State A A/C 2 *32

8. RIH w/cmt ret on WS. Set cmt ret 50' above perfs in 8-5/8". Sqz w/sufficient cmt to circ to surface. Snap out of cmt ret. Spot 100' cmt plug 150-250'. Spot 50' cmt plug at surface.
9. Cut off 5½" csg 5' below GL. Weld on steel plate. Set P&A marker. Clean location.

RECEIVED

AUG - 6 1984

O.C.D.
HOBBS OFFICE

1