NO. OF COPIES RECEIVED			Form C-103			
DISTRIBUTION						
SANTA FE	NEW MEXICO OIL CONS	NEW MEXICO OIL CONSERVATION COMMISSION				
FILE						
U.S.G.S.			5a. Indicate Type of Lease			
LAND OFFICE			State X Fee			
OPERATOR			5. State Oil & Gas Lease No.			
			157			
SUNE DO NOT USE THIS FORM FOR T USE **APPLIC						
1	ROPOSALS TO DRILL OR TO DEEPEN OR PLUG E ATION FOR PERMIT -** (FORM C-101) FOR SUC		7. Unit Agreement Name			
OIL X GAS WELL	OTHER-					
2. Name of Operator	6. Farm or Lease Name					
Atlantic Richfield C	ompany		State 157 "D"			
3. Address of Operator			9. Well No.			
P. O. Box 1710, Hobb	s, New Mexico 88240		2			
4. Location of Well		· · · · · · · · · · · · · · · · · · ·	10. Field and Pool, or Wildcat			
UNIT LETTER K	2310 FEET FROM THE South	1 INE AND 1650 SEET 500	Arrowhead Gravburg			
		CINE AND FEET FROM				
THE West LINE, SEC	TION 12 TOWNSHIP 225	RANGE36ENMPM				
		NMPM	· XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII			
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County			
	3480	' GR	Lea Allilli			
16. Check	Appropriate Box To Indicate N					
	INTENTION TO:	•	T REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING			
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT			
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB				
—		OTHER	<u>ل</u> ے			
OTHER			· ·			
17. Describe Proposed or Completed work) SEE RULE 1103.	Operations (Clearly state all pertinent det	ails, and give pertinent dates, including	z estimated date of starting any proposed			
TD 3759! DDD 2504!	This wall is successfield		· · · · · · · · · · · · · · · · · · ·			
1D 3739, PBD 3394 .	This well is presently	in a temporary abandonme	ent status w/a CIBP set @			
10.2/4" op 45# and	cmt. 7" csg test indica	ated hole in csg from 47	′9–491 ′.			
7" OD $45#$ csg se	et @ 311' & cmtd w/250 sx	. Circ to surf.				
	3656' & cmtd w/250 sx.		•			
	andon in the following man		-			
1. Kig up, kill well,	, install BOP. Spot heavy	y gelled mud between all	. cmt plugs.			
2. RIH w/dump baller,	spot 2 sx cmt @ PBD 3594	•				
3. Run free point & pull 7" csg from approx 2500'.						
4. Spot 45 sx Cl C cmt w/4% gel & 2% CaCl (100' plug)across 7" OD csg stub.						
5. Spot 45 sx Cl C cmt w/4% gel & 2% CaCl (100' plug) across top of salt @ 1350'.						
6. Spot 60 sx Cl C cmt w/4% gel & 2% CaCl (100' plug) across bottom of 10-3/4" OD csg shoe						
@ 311'.						
7. Spot 10 sx cmt @ surface, install regulation dry hole marker, clean & level location						
for abandonment.	at have of sul	· · · · · · · / /	1 1 10			
in a land in	I have it sal	t if not been	a prya.			
100 page						
18. I hereby certify that the informati	on above is true and complete to the best of	of my knowledge and belief.				
SIGNED ATL						
	TITLE I	Dist. Drlg. Supv.	DATE11/5/75			
	TITLE I	Dist. Drig. Supv	DATE11/5/75			
<u> </u>	TITLE I	Dist. Drig. Supv	DATE11/5/75 			
APPROVED BY	action of the	Dist. Drig. Supv.	DATE			

CONDITIONS OF APPROVAL, IF ANY:



ATLANTIC RICHFIELD COMPANY Blow Out Preventer Program

Lease	Name	State	157	"D"	
•	. •				

Well No. 2

Location 2310' FSL & 1650' FWL Sec 12, T22S, R36E, Lea Co.

BOP to be tested before installed on well and will be maintained in good working condition during workover. All wellhead fittings to be of sufficient pressure to operate in a safe manner.

1

DEIVED

10. 7 1975

CIL CONSERVATION COMM. HORES, N. M.