

South Eunice Unit 710.12

Pg 2

and remove out excess cement. POC H. WOC 24 hrs.

5. Drill out cement sub, float collar & float shoe to 3665'. Circulate hole clean & POC H.
6. G1H w/ SN, Hg, crossover & 2 7/8" Hg. String into lower Sealbore extension & pressure test squeeze to 1000 psi for 15 mins. Clean out well.
7. Drill out Cal-seal plug at 3665' & clean well out to 3820'. Circulate well clean & POC H.
8. G1H w/ SN, Hg, crossover & 2 7/8" Hg. Land SN in lower Sealbore extension at 3655'. Load back side & pressure to 500 psi.
9. Acidize 3678'-3814' at 3 BPM w/ surface pressure of 2000 psi w/ 90 bbls 15% HCL-FC acid w/ 60 gals Chicken-Sol inhibited for 24 hrs at 100°F and 500# graded rock salt mixed in 4 bbls gelled 9" brine in 3 equal stages. Flush w/ 100 bbls 9" brine. Swab back load. POC H.
10. G1H w/ SN, anchor seal assembly & 2 3/8" PC Hg. Load backside w/ mixture of 3 gals Conoco No. 1 pkr fluid plus 4 gals Conoco No. 2 pkr fluid mixed in 80 bbls 2% KCl TFW. Latch Hg into pkr at 3560'. Return well to injection. Let well stabilize for 1 week.
11. G1H w/ 4 arm x 30" caliper & wireline. Run caliper from 3820'-3550' & POC H.
12. Run injection profile survey.

If you need further information, contact Jay Vasher at 347-5866