Form \$100-5 (November 1983) TED STATES JUBMIT IN TR., "CATE• : JOINS AUGUST 11, 1988 ST OF THE INTERIOR "Other Instructions on re-DEPARTML Formerly 9-3317 LEASE DESIGNATION AND HERIAL SH BUREAU OF LAND MANAGEMENT IF INDIAN, XLLOTTEE ON SUMDRY NOTICES AND REPORTS ON WELLS 3 (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.) Ī. 7. UNIT AUREEMENT NAME OIL WELL GAS WELL i i OTHER 2. NAME OF OFERATOR 8. FARM OR LEADE NAME .OLOCO Ø 3. ADDRESS OF OPEBATOR 8 WELL NO. LOCATION OF WELL (Report location clearly and in accordance See also space 17 below.) At surface 4. with any State 10. FIELD AND POOL, OR WILDCAT 65 1450/31990/8 Mait T 225--361 14. PERMIT 15 ELEVATIONS (Show whether DF, RT, GR. etc.) 12 COUNTY 13. STATE OR PARISE F OJA D 18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO : SUBSEQUENT ESPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT NULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDONMENT* REPAIR WELL CHANGE PLANS (Other) (Other) (Nors: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* PAH this well according to 40 attached edure, 77 m ^o ٢n < m -ഹ 8. I hereby certify that the foregoing is test and correct T SIGNED **AP**TITLE DATE (This space for Federal or State office use) APPROVED BY TITLE CONDITIONS OF APPROVAL, IF. ANY : DATE

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RECEITO

MAY 1 0 1990 CCC HOBBS OFFICE

MEYER B-22 NO. 1 PLUG AND ABANDON

| <u>Location</u> : | 1650' FSL & 990' FEL, Sec. 22, T-223, R-36E Lea County, NM | | | | | | |
|---------------------|---|--|--|--|--|--|--|
| <u>Elevation</u> : | 3512' DF (10' AGL) | | | | | | |
| <u>Completion</u> : | Jalmat Yates TD: 3450' 4-3/4" Open Hole (3088'-3450') | | | | | | |

Casing/Tubing Specifications:

| O.D. | Weight Grade | Depth | Drift | Collapse | Burst | Capacity 3 | |
|-------------|-----------------|-------|--------|----------|--------|------------|-------------|
| <u>(in)</u> | <u>(lbs/ft)</u> | (ft) | (in) | (psi) | (psi) | (bb1/ft) | (ft^3/ft) |
| 10-3/4" | 32.75 H-40 | 356 | 10.036 | 880 | 1,820 | .1009 | .5665 |
| 5-1/2" | 17.0 J-55 | 3016 | 4.767 | 4,910 | 5,320 | .0232 | .1305 |
| 5-1/2" | 15.5 J-55 | 3088 | 4.825 | 4,040 | 4,810 | .0238 | .1336 |
| 2-7/8" | 6.5 N-80 | | 2.347 | 11,160 | 10,570 | .00579 | .03250 |

10-3/4" casing set @ 356' with 300 sx cement circulated to surface. 5-1/2" casing set @ 3088' with 825 sx cement. TOC @ 715' by temperature survey.

Use safety factor of 70% for collapse and burst pressures. Assume 2-7/8" workstring will be used.

<u>Notes:</u> 1. All cement slurry used in this procedure shall be Class "C" with 2% CaCl, mixed @ 14.8 ppg. 2. All mud shall be 9.5 ppg with 25 lbs gel/bbl brine.

- 3. Call Kandy Lawson to notify BLM prior to commencing any work.

Recommended Procedure:

- 1. Prepare well for P&A:
 - A. MIRU. Bleed well pressure down. Kill well with 10 ppg brine if needed.
 - B. ND wellhead and NU BOP. TOOH and LD 2-3/8" production tubing.
 - C. PU and TIH w/4-3/4" bit, 5-1/2" casing scraper, and 2-7/8" workstring to 3060'. POOH.
- 2. Pump bottom cement plugs:
 - A. MIRU cement services.
 - B. GIH w/5-1/2" cement retainer, setting tool, and WS. Set cement retainer @ 3030'.
 - 1. Test tubing to 1000 psi.
 - 2. Sting out of retainer and circulate hole with 70 bbls mud. Test casing to 500 psi.
 - 3. Sting back into retainer. Establish a pump-in rate.

Meyer B-22 No. 1 Plug and Abandon Page 2

i.

- C. Pump 50 sx cement to fill up 5-1/2" casing and open hole from 3030' to 3450'. Maximum surface pressure is 1000 psi.
- D. Sting out of retainer and spot 25 sx cement on top from 3030' to 2780'. Displace tubing with 16 bbls mud.
- E. POOH laying down WS to 1940'. Load hole with 2 bbls mud.
- F. Pump 15 sx cement and displace with 10 bbls mud to spot plug across top of salt from 1940' to 1790'.
- G. POOH laying down WS.
- 3. Circulate cement up surface casing and set surface plug:
 - A. MIRU wireline services.
 - B. RIH with a 4" casing gun loaded 4 JSPF (120° phase, .4" EHD) and CCL.
 - C. Perforate 5-1/2" production casing @ 410'. POOH.
 - D. GIH w/l joint 2-7/8" tubing. Close BOP. Pump 40 bbls mud to load hole and establish circulation up 10-3/4" x 5-1/2" annulus.
 - E. Pump 180 sx cement (15 sx excess) to fill up 10-3/4" x 5-1/2" annulus and set surface plug in 5-1/2" casing.
 - Note: If cement does not circulate to surface, pump 25 sx down 10-3/4" x 5-1/2" annulus.
 - F. POOH with tubing.
 - G. RD wireline and cement services.
- 4. Prepare surface location for abandonment:
 - A. ND BOP and cut off all casing strings at the base of the cellar or 3' below the final restored ground level (whichever is deeper). RDMO pulling unit.
 - B. Fill the casing strings (if necessary) from the cement plug to surface with cement.
 - C. Cover the wellbore with a metal plate at least 1/4" thick, welded in place, or a cement cap extending radially at least 12" beyond the 10-3/4" casing and at least 4" thick.
 - D. Erect an abandonment marker according to the following specifications:
 - 1. Marker must be at least 4" diameter pipe, 10' long with 4' above restored ground level, and embedded in cement.
 - 2. Marker must be capped and inscribed with the following well information:

Meyer B-22 No. 1 Unit I, Sec. 22, T-22S, R-36E Lea County, NM Date

Note: 1/4" metal plate can be welded to marker and then to the casing after the marker is set in cement.

Meyer B-22 No. 1 Plug and Abandon Page 3

- Cut off dead-man anchors below ground level and remove markers. Ε. Fill in cellar and workover pit.
- F. Remove all equipment, concrete bases, and pipe not in use.
- G. Clean and restore location to its natural state. Reseed according to BLM requirements.
- 5. Send a copy of the well service report and final P&A schematic to Kandy Lawson in the Hobbs Office so the proper forms can be filed.

Approved:

Von C. aduddeel Engineering Technician

a. Milly ente

Supervising Production Engineer

Mindrad L. Morcien

Division Engineering Manager

Production Superintendent

TCA:mjm MB-22NO1.PRO

<u>2-2-90</u> Date

<u>2-3-90</u> Date

4/24/90 Date

RECEIVED MAY 1 0 1990 OCD HOBBS OFFICE MEYER B-22 No. 1

1650' FSL & 990' FEL ELEVATION: 3512 DE UNIT I, SEC. 22, T-225, R-36E 3502 GL 4"PEA MARKER CELLAR RESTORED GL BACKFILL CELLAR WI SAND TO CONTOUR CUT CASING OFF AT BASE OF CELLAR OR 3'BELOW GL 180 SX Class "C" w/2% Calla 103/4", 32,75#, H-40 @ 356 W/300 54 (Circ). From Surface to Alo (Circ). Perf 4.JSPF @410! TOC @ TIS' (Temp. Survey). Tops: 9.5 ppg Anhydrite Mud 1445' Salt 18651 B. Salt 29821 155x Class "C" W/27e CaCl2 Yates 3200' From 1790' to 1940', 9,5ppg Mud 25 5x Class C" W/2% Ca Cla From 2180 to 3030! + Cement Retainer set & 3030! 51/2", 17 \$ 15,5 #, J-55 @ 3088 W/8253X. 50 5x Class "C" W/2 % Callz Jalmat Vate= From 3030' to 34.50' - 27 4. 74" Open Hole (Not Shot or Acidized). TD: 3450'

TCM

Disculation shoet

HAFS Log County, NM

1-17-91

-Propesed PAR-