

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI-
(Other Instructions
verse side)

Form approved,
Budget Bureau No. 1004-0135
Expires August 31, 1985

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Injection Well</u>	2. NAME OF OPERATOR <u>Conoco Inc.</u>	3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) <u>At surface</u> <u>1980' FSL & 660' FEL - Unit Letter I</u>	5. LEASE DESIGNATION AND SERIAL NO. <u>LC-030133B</u>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	7. UNIT AGREEMENT NAME <u>South Eunice Unit</u>	8. FARM OR LEASE NAME <u>South Eunice Unit</u>	9. WELL NO. <u>24</u>	10. FIELD AND POOL, OR WILDCAT <u>Eunice 7 Rvs Queens</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>22-22S-36E</u>	12. COUNTY OR PARISH <u>Lea</u>	13. STATE <u>NM</u>
14. PERMIT NO. <u>30-025-08998</u>	15. ELEVATIONS (Show whether OF, RT, GR, etc.)											

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) CO₂ Perf. Install Liner & Casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work started 6/20/88. Clean out to 3825'. Run caliper 3000'. Perf 3678'-3770' w/2 spf. Plug back to 3680'. Tag sand at 3605'. Clean out metal cuttings, sand & scale to 3825'. Plug back to 3680'. Run 3 1/2" fiberglass liner & 5 1/2" pki. Set pki at 2463'. Pki would not set on bottom. Dull out pki & liner for 11 days. RIH w/new liner & pki. Set pki at 3388'. Cement w/115 sxs cement. Dull out cement & test liner to 600 psi. Dull out cat-sal & sand to 3825'. Acidize flood zone from 3675'-3784' w/90 bbls 15% HCL. Run Hg to 3388' & latch into pki. Return well to production. Work Completed 7/22/88.

18. I hereby certify that the foregoing is true and correct

SIGNED John Finney, Jr.

TITLE Administrative Supervisor

DATE January 16, 1989

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 20 1989

*See Instructions on Reverse Side

SJS
CARISBUD, NEW MEXICO