

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Federal Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>Injection Well</u>	7. Unit Agreement Name <u>South Eunice Unit</u>
2. Name of Operator <u>Conoco Inc.</u>	8. Farm or Lease Name <u>South Eunice Unit</u>
3. Address of Operator <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. Well No. <u>24</u>
4. Location of Well UNIT LETTER <u>I</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>east</u> LINE, SECTION <u>22</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat <u>Eunice 7 RVRS Queen</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOBS ☐
PLUG AND ABANDON ☐	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐
OTHER <u>CO, Repair, Install Lines & Acidize</u> ☒	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. MIRR, Pressure test backside to 500 psi for 30 mins to test csq integrity if fails pull up hole 1 ft, reset pkr & retest, if holds, release Baker AD-1 pkr & TOOH.
2. Clean out well to 3825' & POOH.
3. Run csq scraper to 3825' & POOH.
4. Run caliper from 3825' - 3300' & POOH.
5. Perf intervals 3678' - 3770' w/ 2 jsf for total of 68 shots. POOH.
6. Dump 20' of 12/20 sand down csq to plug well back from 3825' to 3680'. G1H w/ bailer & tag sand at 3680'. If sand below 3680', dump additional sand, if above 3680', POOH w/ bailer. G1H w/ 4 3/4" bit & 2 7/8" Hg & reverse out to 3680'. G1H w/ dump bailer & dump 1/2 sx cal-seal plug from 3680' - 3675'. WOC 1 hr & tag cmt at 3675' & POOH.
7. G1H w/ Gidverson 3 1/2" float shoe, float collar, 3 1/2" x 5 1/2" centralizer, 1 1/2" aluminum cmt sub, 5' x 2.812" seal bore extension & 9' to 3 1/2"

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED DF FINNEY TITLE Administrative Supervisor DATE February 3, 1988

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE FEB 8 - 1988

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 5 1938

OCD
HOBS OFFICE