Submit 3 Copies to Appropriate District Office	State of New Mex Energy, Minerals and Natural R	,	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs NM 88240 DISTRICT II 811 S. 1st Street, Artesia, NM 882	Santa Fe. New Mexico	88	WELL API NO. 30-025-09934 5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 3	87410		STATE FEE X
(DO NOT USE THIS FORM FO DIFFERENT (FO	NOTICES AND REPORTS ON WEL OR PROPOSALS TO DRILL OR TO DEEPEN O RESERVOIR. USE "APPLICATION FOR PERI DRM C~101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name W.S. Marshall B
	S OTHER		
2. Name of Operator Marathon 011 Company			8. Well No.
3. Address of Operator P.O. BOX 2409, Hobbs, N 4. Well Location	IM 88240		9. Pool name or Wildcat Blinebry 011 & Gas
Unit Letter <u>N</u> :	589 Feet From The South	Line and205	1 Feet From The West Line
Section 27	Township 21-S Ran 10. Elevation (Show whether GL 3	er DF, RKB, RT, GR, etc.)	MPM Lea County
	k Appropriate Box to Indicate I F INTENTION TO:	1	Report, or Other Data SEQUENT REPORT OF:
		REMEDIAL WORK	
TEMPORARILY ABANDON		COMMENCE DRILLING C	
PULL OR ALTER CASING		CASING TEST AND CEM	
OTHER:		OTHER: Add pay/st:	imulate Blinebry formation.

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Marathon 011 Company has completed the work on the above referrence well. Please see attachment for summary of work performed.

I hereby certify that the information above is true and com skgnature		DATE 4/21/97
TYPE OR PRINT NAME Kelly Cook		TELEPHONE NO. 393-7106
his space for State Use) ORIGINAL SIGNED BY DISTRICT 1 SUF	OF AIS WILLIAMS	ne: <b>3.1.10</b> 0
PPROVED BY	TITLE	DATE JUN 11 199

Marathon Oil Company Marshall B Well No. 1 C-103 Sub. Attachment February 27, 1997

- 1. MIRU pulling unit. POOH w/rods and pump. ND wellhead. Release TAC. NU BOP. POOH w/TAC and tbg. RIH w/RBP, set at 60'. Test to 1000 psi, OK. Retrieve RBP, POOH. RIH w/bit scraper to 6058'. POOH. RIH w/RBP and treating pkr, set RBP at 5760', set pkr at 5740'. Test RBP to 1000 psi, OK. PUH set pkr at 5420'. Test csg. POOH w/pkr and tbg. Drop ball catcher.
- NU frac valve. RU wireline company. Perforate Blinebry formation 5490-5520', 5524-42', 5552-58', 5576-80', 5590-94', 5598-5602', 5614-28', 5670-5712' w/2 JSPF, 120 degree phasing. Total of 260 holes. RD wireline company. ND frac valve.
- 3. RIH w/pkr and retrieving tool, set at 5430'. RU acid company. Acidized Blinebry formation w/6500 gals of 15% Ferchek acid and dropped 300 ball sealers. RD acid company. RU to swab. Swab well.
- 4. Release pkr at 5430'. RIH to 5760' and retrieve ball catcher. POOH w/catcher and pkr. RU testers. Test tbg, OK. RD testers. RIH set pkr at 5430'.
- 5. RU frac company. Frac Blinebry w/122,000 gals of 20# Delta cross-linked linear gel and 297,000 # 16/30 sand. RD frac company.
- 6. RU slickline, tag sand at 5518'. RD slickline. Rel pkr at 5465', POOH. RIH w/overshot to 5465'.
- 7. RU foam air unit. Wash sand off Blinebry perfs from 5518-5760'. Circulate. Rel RBP at 5760'. POOH.
- 8. RIH release pkr at 5430', POOH. Change out pipe rams to 2 3/8". RIH w/pkr, set at 5465'. FIH w/tbg, tag sand at 5874'. POOH w/tbg. RIH w/tbg to 5817'. RU foam air unit, wash sand off perfs from 5874-PBTD 6058'. Circulate. RD foam air unit.
- 9. RIH w/178 jt's 2 3/8" 4.70# H-40 tbg to 5523'. SN at 5490'. ND BOP. NU wellhead. RDMO pulling unit. Open well to battery.

H:Reg/C-103/Marshb1.sub