

CIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATION	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR REPAIR - (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☒ OTHER ☐ Triple Completion - Oil & Gas	7. Unit Agreement Name /Skaggs Grayburg Unit
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name L.R. Kershaw & Skaggs Grayburg Unit
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 8 Unit Well 11
4. Location of Well UNIT LETTER D 660' FEET FROM THE North LINE AND 990' FEET FROM West 13 TOWNSHIP 20-S RANGE 37-E N.M.P.M.	10. Field and Pool, or Wildcat East Weir Blinebry, Eumont Gas, Skaggs Grayburg
11. Elevation (Show whether DF, RT, GR, etc.) 3565' (DF)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER Repair casing leak & Treat ☒	

17. Description Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

1. Rigged up.
2. Clean out Blinebry. Clean out Drinkard to 4024'.
3. Set CIBP in Blinebry @ 4050'. Spot cement from 4050-4008'. Set CIBP @ 3800'. Blinebry P&A.
4. Set CIBP in Drinkard @ 3890' & 3800'. Drinkard P&A.
5. Set CIBP in Eumont @ 3720'. Ran cement retainer & set @ 3547'. Squeeze down Eumont w/100 sx. Class C cement. Perf. Eumont w/2 JS @ 1955'. Set CIBP @ 1950'. Dump 42' cement on plug from 1950-1908'. Perf. w/2 JS @ 1410'. Squeeze perfs @ 1410' w/300 sx Class 'C' cement. Cement circulated.
6. Squeeze 9-5/8" csg w/100 sx. Class 'C' cement.
7. Drill out Skaggs-Drinkard plugs 3800' & 3890'. Clean out junk in hole.
8. Install pumping equipment. Test and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 5-30-80

APPROVED BY [Signature] TITLE DATE 5-30-80

CONDITIONS OF APPROVAL, IF ANY:
Eumont & Weir Bl. (Lea)
m/12/5/80