

6. Run 1-5/8" Drill Pipe W/packer and set @ 5700'.
7. Acidize Blinebry perforations 5768'-5976' w/3000 gals. 15% acid in 15 stages using 4 ball sealers after each stage.
8. Pull drill pipe. Log well.
9. Frac Blinebry perforations w/24,000 gals. gelled lease crude in 3 stages using 1# 20/40 sand, 1/40# Adomite per gal. and 50# gel per 1000 gals.
10. Swab, test, and place Blinebry zone on production.
11. Drill out cement in Drinkard & pull RBP.
12. Perforate 2-7/8" OD casing ('Z' String) W/I JSPF from 6786'-6790'; W/I JSPI @ 6793', W/I JSPF from 6798-6802'; 6808'-6812'; & 6842'-6845'.
13. Run 1-5/8" Drill Pipe W/packer and set @ 6700'.
14. Acidize Drinkard perforations 6786-6845' W/6000 gals. 15% acid in 4 stages. Precede 1st stage w/9 ball sealers and follow each stage w/5 ball sealers.
15. Pull drill pipe. Swab, test, place Drinkard on production.

RECEIVED

JUN 22 1970

**OIL CONSERVATION COMM.
HOBBS, N. M.**