Image: A to Compare the second sec	NO. OF COMILS + FELINED		Form C-103 Supersedes Old	
Uses Image: State of the second of the s	SANTA FE NEW MEXI	CO OIL CONSERVATION COMMISSION	C-102 and C-103	
OPENATION Image: Subject of the second state of the second s	U.S.G.S.			
as and the rest of the second state				
20	· · · · · · · · · · · · · · · · · · ·		A-2614	
************************************	USE "APPLICATION FOR FERMIT (FORM	EPORTS ON WELLS EPER OR FLUG BACK TO A DIFFERENT RESERVOIR. C-101) FOR SUCH PROPOLALS.)		
Marzethon 011 Company McDonald State A/C 2 P. O. Box 2409, Hobbs, New Nexico 88240 29 P. O. Box 2409, Hobbs, New Nexico 88240 29 In Finder State 16 Finder State A/C 2 With Nexico 8 Veill 21 With Nexico 8 Veill 330 The East incluster incluste	OIL X GAS OTHER-			
1. decrete el Operator P. O. Box 2409, Hobbs, New NexIco 86240 1. Locates el Vell 1. Locates el Ve	-			
2. Locations of Veli II. Field was Pack, or Wilded with Vertice II. vert vert vert vertice II. Vert vert vert vert vert vert vert vert v	3. Accress 6: Operator		9. Well No.	
Instrume Instrume North Instrume In		88240		
The				
3452' GL; 3462' K3 Lea Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Subsequent REPORT OF: Subsequent Report of Other Data Notice Called Subsequent Report of Other Data Subsequent Report of Other Data Subsequent Report <				
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERNO CARNED CONSTRUCTION TO: SUBSEQUENT REPORT OF: ALTERNO CARNED CONSTRUCTION TO: CONSTRUCT ON DATABOL CONSTRUCTION CONSTRUCT	11111111111111111111111111111111111111	(Show whether DF, RT, GR, etc.)	12. County	
Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: " CONTRET CALLON ALLOOM NOTICE OF INTENTION TO: " CONTRET CALLON ALLOOM NULL OF ALLOOM	<u></u>			
VELICODATIVE CARRE CONTROL CLARKE CARRE CONTROL CARRENT AND CLARKET DELLING OWNER CONTROL OF AND CLARKET DELLING OWNER DELING OWNER CLARKET DELING OWNER CLARKET DELING OWNER CLARKET DELING OWNER DELING OWNER CLARKET DELING OWNER DELING OWNER DELING OWNER DELING OWNER DELING OWNER	Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
 27. Descript Proposed or Completed Covertions (Clearly state all perinent details, and give perinent dates, including estimated date of starting any propose week/ state full = 103. 27. Descript Proposed or Completed Covertions (Clearly state all perinent details, and give perinent dates, including estimated date of starting any propose week/ state full = 103. 27. Descript Proposed or Completed Covertions (Clearly state all perinent dates, and give perinent dates, including estimated date of starting any propose week/ state full = 103. 27. Descript Proposed or Completed Covertions (Clearly state all perinent dates, including estimated date of starting any propose week/ state full = 103. 27. Descript Proposed or Completed Covertions (Clearly state all perinent dates, including estimated date of starting any propose week/ state full = 103. 27. Descript Proposed or Completed Covertions (Clearly state all perinent dates, including estimated date of starting any propose week/ states for the text of the text of the text of the text of text of the text of text of	PERFORM REMEDIAL WORK			
 7. Deterine Proposed or Completed Operations (Clearly state all pertinent datas, and give pertinent datas, including estimated date of starting ony propose (area) at a starting on propose (area) at a starting on the start of the	PULL OR ALTER CASING			
 Drilled 7 7/8" hole to 6710' Ran Gamma Ray-Compensated Neutron from T.D. to surface with formation density recorded from T.D. to 2400' and Caliper recorded from T.D. to 1300'. Ran Gamma Ray-Dual Laterolog from T.D. to 2400'. Ran 5 1/2", 15.5#, K-55 casing to 6710' with stage cementing tool @ 3120'. Ran one centralizer on bottom three joints and one on every other joint to 5320'. Ran two centralizers and two baskets above and below stage tool. Total 22 centralizers. First Stage - Cemented below stage tool with 705 sacks Class "C" with 2% Lodense and 1/4# Celloflake per sack, followed by 300 sacks Class "C" Neat. Bumped plug with 2800 psi, released pressure, float held 0K. Opened stage tool and circulated five hours. Circulated 75 sacks to pit. Second Stage - Cemented above stage tool with 1,390 sacks Class "C" with 2% Lodense and 1/4# Celloflake per sack followed by 200 sacks Class "C" Neat. Bumped plug with 2500 psi. Circulated 200 sacks to pit. Cut off 5 1/2" casing, installed slips, waited on cement. Drilled out stage tool. Tested casing to 1500# for 15 mins. Held 0K. PBTD 6672'. Ran Gamma Ray-Cement Bond-Collar Log. Cement bond log ipdicated to gat of the state of th	OTHER			
 2. Ran Gamma Ray-Compensated Neutron from T.D. to surface with formation density recorded from T.D. to 2400' and Caliper recorded from T.D. to 1300'. Ran Gamma Ray-Dual Laterolog from T.D. to 2400'. 3. Ran 5 1/2", 15.5%, K-55 casing to 6710' with stage cementing tool @ 3120'. Ran one centralizer on bottom three joints and one on every other joint to 5320'. Ran two centralizers and two baskets above and below stage tool. Total 22 centralizers. 4. First Stage - Cemented below stage tool with 705 sacks Class "C" with 2% Lodense and 1/4% Celloflake per sack, followed by 300 sacks Class "C" Neat. Bumped plug with 2800 psi, released pressure, float held OK. 5. Opened stage tool and circulated five hours. Circulated 75 sacks to pit. 6. Second Stage - Cemented above stage tool with 1,390 sacks Class "C" with 2% Lodense and 1/4% Celloflake per sack followed by 200 sacks Class "C" Neat. Bumped plug with 2500 psi. Circulated 200 sacks to pit. 7. Cut off 5 1/2" casing, installed slips, waited on cement. 8. Drilled out stage tool. Tested casing to 1500# for 15 mins. Held OK. PBTD 6672'. 9. Ran Gamma Ray-Cement Bond-Collar Log. Cement bond log indicated on first stage @ 3418', second stage circulated. A. Drilled out stage circulated. A. Drilled OK. PBTD 6672'. A. Drill	17. Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103.	l pertinent details, and give pertinent dates, including	estimated date of starting any proposed	
 2. Ran Gamma Ray-Compensated Neutron from T.D. to surface with formation density recorded from T.D. to 2400' and Caliper recorded from T.D. to 1300'. Ran Gamma Ray-Dual Laterolog from T.D. to 2400'. 3. Ran 5 1/2", 15.5%, K-55 casing to 6710' with stage cementing tool @ 3120'. Ran one centralizer on bottom three joints and one on every other joint to 5320'. Ran two centralizers and two baskets above and below stage tool. Total 22 centralizers. 4. First Stage - Cemented below stage tool with 705 sacks Class "C" with 2% Lodense and 1/4% Celloflake per sack, followed by 300 sacks Class "C" Neat. Bumped plug with 2800 psi, released pressure, float held OK. 5. Opened stage tool and circulated five hours. Circulated 75 sacks to pit. 6. Second Stage - Cemented above stage tool with 1,390 sacks Class "C" with 2% Lodense and 1/4% Celloflake per sack followed by 200 sacks Class "C" Neat. Bumped plug with 2500 psi. Circulated 200 sacks to pit. 7. Cut off 5 1/2" casing, installed slips, waited on cement. 8. Drilled out stage tool. Tested casing to 1500# for 15 mins. Held OK. PBTD 6672'. 9. Ran Gamma Ray-Cement Bond-Collar Log. Cement bond log indicated on first stage @ 3418', second stage circulated. A. Drilled out stage circulated. A. Drilled OK. PBTD 6672'. A. Drill	1. Drilled 7 7/8" hole to 6710'			
 3. Ran 5 1/2", 15.5#, K-55 casing to 6710' with stage cementing tool @ 3120'. Ran one centralizer on bottom three joints and one on every other joint to 5320'. Ran two centralizers and two baskets above and below stage tool. Total 22 centralizers. 4. First Stage - Cemented below stage tool with 705 sacks Class "C" with 2% Lodense and 1/4# Celloflake per sack, followed by 300 sacks Class "C" Neat. Bumped plug with 2800 psi, released pressure, float held OK. 5. Opened stage tool and circulated five hours. Circulated 75 sacks to pit. 6. Second Stage - Cemented above stage tool with 1,390 sacks Class "C" with 2% Lodense and 1/4# Celloflake per sack followed by 200 sacks Class "C" Neat. Bumped plug with 2500 psi. Circulated 200 sacks to pit. 7. Cut off 5 1/2" casing, installed slips, waited on cement. 8. Drilled out stage tool. Tested casing to 1500# for 15 mins. Held OK. PBTD 6672'. 9. Ran Gamma Ray-Cement Bond-Collar Log. Cement bond Log indirated top of first stree @ 3418', second stage circulated. A. Horeby certify that the information above is true and complete to the best of my knowledge #@bidec.PNR AVED. 9. Orig. Signed by Jerry Sector 9. Orig. Signed by June Production Engineer over April 17, 1978 	from T.D. to 2400' and Caliper recorded from T.D. to 1300'. Ran Gamma Ray-Dual Laterolog			
 centralizers and two baskets above and below stage tool. Total 22 centralizers. 4. <u>First Stage</u> - Cemented below stage tool with 705 sacks Class "C" with 2% Lodense and 1/4# Celloflake per sack, followed by 300 sacks Class "C" Neat. Bumped plug with 2800 psi, released pressure, float held 0K. 5. Opened stage tool and circulated five hours. Circulated 75 sacks to pit. 6. <u>Second Stage</u> - Cemented above stage tool with 1,390 sacks Class "C" with 2% Lodense and 1/4# Celloflake per sack followed by 200 sacks Class "C" with 2% Lodense and 1/4# Celloflake per sack followed by 200 sacks Class "C" Neat. Bumped plug with 2500 psi. Circulated 200 sacks to pit. 7. Cut off 5 1/2" casing, installed slips, waited on cement. 8. Drilled out stage tool. Tested casing to 1500# for 15 mins. Held 0K. PBTD 6672'. 9. Ran Gamma Ray-Cement Bond-Collar Log. Cement bond log indicated top of first stage 0 3418', second stage circulated. 6. Ibrety certify that the information above is true and complete to the best of my knowledge 460 bidded WED. 6. Ibrety certify that the information above is true and complete to the best of my knowledge 460 bidded WED. Orig. Signed by Jerry Sector Witte	3. Ran 5 1/2", 15.5#, K-55 casing to 6710' with stage cementing tool @ 3120'. Ran one			
 1/4# Celloflake per sack, followed by 300 sacks Class "C" Neat. Bumped plug with 2800 psi, released pressure, float held OK. 5. Opened stage tool and circulated five hours. Circulated 75 sacks to pit. 6. Second Stage - Cemented above stage tool with 1,390 sacks Class "C" with 2% Lodense and 1/4# Celloflake per sack followed by 200 sacks Class "C" Neat. Bumped plug with 2500 psi. Circulated 200 sacks to pit. 7. Cut off 5 1/2" casing, installed slips, waited on cement. 8. Drilled out stage tool. Tested casing to 1500# for 15 mins. Held OK. PBTD 6672'. 9. Ran Gamma Ray-Cement Bond-Collar Log. Cement bond Log indicated top of first stage @ 3418', second stage circulated. 6. Increte certify that the information above is true and complete to the best of my knowledge from biddefail NR CVED. 6. Increte error box 9. Ran Gamma Ray-Cement box 9. Ran Gamma Ray-Cement Bond-Collar Log. Cement bond Log indicated top of first stage @ 3418', second stage circulated. 9. Production stage circulated. 9. Production stage circulated. 9. Production Engineer pare April 17, 1978 	centralizers and two baskets above and below stage tool. Total 22 centralizers.			
 5. Opened stage tool and circulated five hours. Circulated 75 sacks to pit. 6. Second Stage - Cemented above stage tool with 1,390 sacks Class "C" with 2% Lodense and 1/4# Celloflake per sack followed by 200 sacks Class "C" Neat. Bumped plug with 2500 psi. Circulated 200 sacks to pit. 7. Cut off 5 1/2" casing, installed slips, waited on cement. 8. Drilled out stage tool. Tested casing to 1500# for 15 mins. Held OK. PBTD 6672'. 9. Ran.Gamma Ray-Cement Bond-Collar Log. Cement bond Log indicated top of first stage (2) 3418', second stage circulated. 6. I hereby sentify that the information above is true and complete to the best of my knowledge from bottlef. The OVED. 6. I hereby sentify that the information above is true and complete to the best of my knowledge from bottlef. The OVED. 9. Orig. Signed by Jerry Sentified 9. Just 1, 100. 	1/4# Celloflake per sack, followed by 300 sacks Class "C" Neat. Bumped plug with 2800			
 6. Second Stage - Cemented above stage tool with 1,390 sacks Class "C" with 2% Lodense and 1/4# Celloflake per sack followed by 200 sacks Class "C" Neat. Bumped plug with 2500 psi. Circulated 200 sacks to pit. 7. Cut off 5 1/2" casing, installed slips, waited on cement. 8. Drilled out stage tool. Tested casing to 1500# for 15 mins. Held OK. PBTD 6672'. 9. Ran Gamma Ray-Cement Bond-Collar Log. Cement bond log indicated top of first stage @ 3418', second stage circulated. 6. I hereby certify that the information above is true and complete to the best of my knowledge from bolies. PRIME VED. 6. I hereby certify that the information above is true and complete to the best of my knowledge from bolies. PRIME VED. 6. I hereby certify that the information above is true and complete to the best of my knowledge from bolies. PRIME VED. 6. I hereby certify that the information above is true and complete to the best of my knowledge from bolies. PRIME VED. 6. I hereby certify that the information above is true and complete to the best of my knowledge from bolies. PRIME VED. 6. I hereby certify that the information above is true and complete to the best of my knowledge from bolies. PRIME VED. 6. I hereby certify that the information above is true and complete to the best of my knowledge from bolies. PRIME VED. 6. I hereby certify that the information above is true and complete to the best of my knowledge from bolies. PRIME VED. 6. I hereby certify that the information above is true and complete to the best of my knowledge from bolies. PRIME VED. 6. I hereby certify that the information above is true and complete to the best of my knowledge. PRIME VED. 6. I hereby certify that the information above is true and complete to the best of my knowledge. PRIME VED. 6. I hereby certify that the information above is true and complete to the best of my knowledge. PRIME VED. 			to pit.	
 7. Cut off 5 1/2" casing, installed slips, waited on cement. 8. Drilled out stage tool. Tested casing to 1500# for 15 mins. Held OK. PBTD 6672'. 9. Ran Gamma Ray-Cement Bond-Collar Log. Cement bond Log indicated top of first stage @ 3418', second stage circulated. 6. I hereby certify that the information above is true and complete to the best of my knowledge in bitief. PROVED VED. 6. I hereby certify that the information above is true and complete to the best of my knowledge in bitief. PROVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge in bitief. PROVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge in bitief. PROVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge in bitief. PROVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge in bitief. PROVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge in bitief. PROVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge in bitief. PROVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge in bitief. PROVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge in bitief. PROVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge in bitief. PROVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge in the bitief. PROVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge in the bitief. PROVED. 6. I hereby certify that the information above is true and certify that the bitief. PROVED. 7. April 17, 1978.<!--</td--><td colspan="4">1/4# Celloflake per sack followed by 200 sacks Class "C" Neat. Bumped plug with 2500</td>	1/4# Celloflake per sack followed by 200 sacks Class "C" Neat. Bumped plug with 2500			
8. Drilled out stage tool. Tested casing to 1500# for 15 mins. Held OK. PBTD 6672'. 9. Ran Gamma Ray-Cement Bond-Collar Log. Cement bond Log indicated top of first stage @ 3418', second stage circulated. 6. I hereby certify that the information above is true and complete to the best of my knowledge and bottlefall NR OVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge and bottlefall NR OVED. Orig. Signed by Jerry Sector Dist. 1, runn				
9. Ran ,Gamma Ray-Cement Bond-Collar Log. Cement bond log indicated top of first stage @ 3418', second stage circulated. 6. I hereby certify that the information above is true and complete to the best of my knowledge from bolief. INROVED. 6. I hereby certify that the information above is true and complete to the best of my knowledge from bolief. INROVED. CENTO	8. Drilled out stage tool. Tested casing to 1500# for 15 mins. Held OK. PBTD 6672'.			
Orig. Signed by Jerry Sexton Dist 1, 1978 TITLE DAYE DAYEDAYEDAYEDAYEDAYEDAYE	 Ran Gamma Ray-Cement Bond-Collar 3418', second stage circulated. 	Log. Cement bond Log indicated	2P. of Einst stage (
Odg. Signed by Jerry Sexton Dist 1, 0002 Title Daye	16. I hereby certify that the information above is true and complet	e to the best of my knowledge and boller TAR AVED.	IVING FUR THE LANDS	
Odg. Signed by Jerry Sexton Dist 1, 0002 Title Daye	SIGNED Willie Re Huch	3	. DAVE April 17, 1978	
Dist 1, TITLE DATE				
	PPROYED BY	111LE	DAYE	
	Dist 12 DIN		URIE	