

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instruction
reverse side)

ATE*

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R. M., OR BLK. AND
SURVEY OR AREA

12. COUNTY OR PARISH

13. STATE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

CONOCO INC.

3. ADDRESS OF OPERATOR

P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface Unit F

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

30-025-26032

Sec. 29-205-38E

Lea

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) open add'l pay & acidize

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU. POOH w/ rods & pump. Scrape csg to 5980'. Spot 6 bbls 15% HCl NE-FE acid from 5942'-5790'.
- ② Perf add'l Blinbry w/ 1 JSF @ 5790', 98', 5808', 23', 30', 46', 50', 57', 61', 74', 79', 83', 5919', 23', 25', 27', 37', 39', 5942'. Set RBP @ 5960' and pkr @ 5900'.
- ③ Acidize w/ 21 bbls 28% HCl-NE-FE and flush to bottom perfs w/ 36 bbls completion fluid. Rel pkr & RBP. Reset RBP @ 5900' & pkr @ 5650'.
- ④ Acidize w/ 36 bbls 28% HCl-NE-FE and flush to bottom perf w/ 42 bbls completion fluid. Reset RBP @ 5960' & pkr @ 5750'. Swab test.
- ⑤ Chemically inhibit perfs w/ 2 drums T-130 (champion) and 1 gal DP in 20 bbls 2% KCl wtr. Over flush w/ 200 bbls 2% KCl wtr.
- ⑥ Rel pkr & RBP. POOH.
- ⑦ Hang well on and rig down.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE 8-6-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 8/26/86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side