

- C. Cover the wellbore with a metal plate at least 1/4" thick, welded in place, or a cement cap extending radially at least 12" beyond the 9-5/8" casing and at least 4" thick.
- D. Erect an abandonment marker according to the following specifications:
 - 1. Marker must be at least 4" diameter pipe, 10' long with 4' above restored ground level, and embedded in cement.
 - 2. Marker must be capped and inscribed with the following well information:

SEMU Blinebry No. 101
Unit D, Sec. 29, T-20S, R-38E
Lea County, NM
Date

Note: 1/4" metal plate can be welded to marker and then to the casing after the marker is set in cement.

- E. Cut off dead-man anchors below ground level and remove markers. Fill in cellar and workover pit.
 - F. Remove all equipment, concrete bases, and pipe not in use.
 - G. Clean and restore location to its natural state. Reseed according to BLM requirements.
7. Send a copy of the well service report and final P&A schematic to the Midland Office so the proper forms can be filed.

APPROVED:

<u>Tom C. Aduddell</u>	<u>9-24-90</u>
Engineering Technician	Date
<u>John F. Murphy</u>	<u>9/29/90</u>
Sr. Production Engineer	Date
<u>Paul E. Porter</u>	<u>10/5/90</u>
Supervising Production Engineer	Date
<u>John A. Bradbury</u>	<u>10/7/90</u>
Division Engineering Manager	Date
<u>Dan Satter</u>	<u>10/8/90</u>
Production Superintendent	Date

TCA\tk\SEMU101.PRO