

DATE: <sup>1-15-92</sup>  
~~11/2/90~~

## Workover Procedure

REVISED <sup>1-15-92</sup>  
          

WELL & JOB: H. S. RECORD # 6

Recomplete

DRILLED: 1981

LAST WORKOVER:

FIELD: Eunice

COUNTY: Le2/NM

BY: GORE

TD: 3959

PBD: 3913'

DATUM:

TUBINGHEAD:

SIZE:

PRESS RATING:

CASING:	<u>SIZE</u>	<u>WEIGHT</u>	<u>GRADE</u>	<u>SET @</u>	<u>SX CMT</u>	<u>TOC</u>
SURFACE:	8-5/8"	24#	K-55	1091'	600	SURFACE
INTER:						
PROD:	5-1/2"	15.5#	K-55	3939	925	SURFACE

PERFORATIONS: 3698'-3881'

SCOPE OF WORK: Recomplete as Jalmat gas well.

## PROCEDURE

1. MIRU PU. Pull rods and pump and LD same. Kill well. NU BOPE.
2. Pull CA. RIH w/casing scraper on tubing to 3550'. POOH. Set a CIBP @ 3650' and dump 35' cement on same. Load and test casing to 1500 psi using 2% KCL water. TIH w/open-ended tubing and a SN. Swab well down to 3000' from surface. POOH w/tubing. ND BOPE and NU frac head w/full opening valve.
3. Perforate Jalmat zone as follows:  
3408 - 3442' at 2 JSPF
  - Use either 60° or 90° spiral phasing
  - Use casing perforating guns that produce a minimum EHD of 0.40"
  - Correlate to Schlumberger DLL dated 9-27-81
  - Use full lubricator
4. Fracture treat above perms using attached procedure from O/A Engineering. Treat through 3-1/2" workstring with packer. Rig up lines to permit immediate flowback and forced closure of frac.  
Frac with 174,980# of 16/30 Brady (Vulcan) sand in 1399 barrels of CO<sub>2</sub> foam at approximately 20-25 bpm. Maximum treating pressure of 4000 psi is recommended.
5. Utilize immediate flowback/forced closure technique. Flow and/or swab test as required. The well should be kept open and flowing for at least the first day of flowback, so a light plant and well flowback watch is required.
6. Check for sandfill w/wireline. Clean out sand if necessary.