Form 9–331 Dec. 1973	N. M. OIL CONS. CHANNESSING P. O. BOX 1090 Budget Burgau No. 42-Black
UNITED STATES	HOBSE MEN MEXICO 88249
DEPARTMENT OF THE INTERIOR	
GEOLOGICAL SURVEY	NM-17441
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME
1. oil gas other PXA	El Alto Grande
2. NAME OF OPERATOR	9. WELL NO.
<u>Amoco Production Company</u>	<u> </u>
3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME
	Wildcat Atoka
P. O. Box 68, Hobbs, New Mexico 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR
Delow.)	AREA 19-22-34
AT SURFACE: 1980' FNL X 2090' FWL, Sec. 19	
AT TOP PROD. INTERVAL: (Unit F, SE/4, NW/4) AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Lea NM
	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
HEI SKI, SK OMER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3461.8' GL
TEST WATER SHUT OFF	
	DECENTEN
PULL OR ALTER CASING	(NOTE: en ort results of multiple completion er zone
	range on Form 9-330.)
CHANGE ZONES	MAY 23 1983
ABANDON*	
(other)	OIL & GAS

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent **most index index** including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

BLM representative on location throughout procedure. Moved in service unit 4-20-83 and killed well with brine water. Released on-off tool and circulated 75 BW down tubing and out casing. Displaced hole and pump 700 bbls brine gel at 250 psi. Pumped 550 bbls brine gel at 3 BPM and 800 psi. Cemented plug with 10 sx class C cement 12,516'-12,432'. Displaced cement and pulled tubing to 11,270'. Cemented 100 sx Class C cement plug. Displaced cement and WOC. Load hole with 14 bbl brine water. Ran tubing and tagged cement at 10,539'. Cir culated with 500 bbls brine. Loaded hole with 35 bbls brine. Pumped 14 bbls brine down tubing. Pulled tubing and seal assembly. Ran 9-5/8" CIBP and set at 10,500'. Capped CIBP with 10 sx class C cement. Pulled up to 7500' and spotted 50 sx class C cement. Pulled up to 5100' and spotted 50 sx Class C cemer plug. Weld lift nipple on 9-5/8" casing. Pulled up on casing and ran freepoint surface Safe Parke, Manu land Voe 1-F. J. Nash, HOU 1-CMH ______ Set @ ______ Ft. Subsurface Step Patve: Manu. and Yoe _____ Ft. 18. I hereby certify that the foregoing is true and correct Ast. Adm. Analyst SIGNED R F DATE

DATE

is space for Federal or State office use) (ORIG. SGD.) DAVID R. GLASS

CONDITIONS OF APPROV ^{ANY}3 **1983**

APPROVED BY



survey. Casing was fr at 3725'. Ran 8-9/32" Jet cut r and cut casing at 3660'. Worked casing free. I led up and laid down 3660' of 5 /8" casing. Ran tubing to 3693' and spot 100 sx class C cement plug. Pulled up and WOC. Ran tubing and tagged cement at 3570'. Pulled tubing to 1886' and spotted 70 sx class C cement. Displaced cement and cut-off wellhead. Spotted 10 sx class C cement at surface. Installed PXA marker and moved out service unit 5-11-83.

OCT 5 1983 HOBBS OFFICE