

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

N. M. OIL CONS. COMMISSION

P. O. BOX 1280  
ROSWELL, NEW MEXICO

Form Approved.  
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐  
2. NAME OF OPERATOR  
Amoco Production Company  
3. ADDRESS OF OPERATOR  
P. O. Box 68, Hobbs, New Mexico 88240  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980' FNL X 2090' FWL, Sec. 19  
AT TOP PROD. INTERVAL: (Unit F, SE/4, NW/4)  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☒  
(other) ☐

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

5. LEASE  
NM-17441  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
El Alto Grande  
9. WELL NO.  
1-Y  
10. FIELD OR WILDCAT NAME  
Wildcat Atoka  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
19-22-34  
12. COUNTY OR PARISH  
Lea  
13. STATE  
NM  
14. API NO.  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3461.8' GL

RECEIVED  
(NOTE: Report results of multiple completion or zone change on Form 9-330.)  
MAR 31 1983

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give surface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Resubmittal of PXA proposal, with changes in the plug settings, per verbal approval Stewart to Herring 3-28-83.

Propose to plug and abandon the subject well per the following:

Move in service unit and pull tubing, XL on-off tool, and Guiberson VI packer. Kill well with 10# brine. Run in hole with cast iron bridg plug and set CIBP at 12,650'. Cap with 35' of cement (4sx). Spot 27 barrels 10# brine with 25# gel/barrel. Spot 100 sx class C neat across 9-5/8" casing shoe at 11,270' and across the top of the 5-1/2" liner at 10750'. WOC. Tag top of cement plug. Cement plug to be at least 100' above top of liner. Spot 200 barrels 10# brine with 25# gel/barrel. Spot 50 sx class C neat at  $\pm 7500'$ . Spot 163 barrels 10# brine with 25# gel/barrel. Spot 50 sx class C neat across the 13-3/8" casing O+6-BLM, R 1-HOU 1-CMH 1-F. J. Nash, HOU

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED David M. Stewart TITLE A. Adm. Analyst DATE 3-29-83

(ORIG. SCD.) DAVID M. STEWART (Federal or State office use)

APPROVED BY JAMES A. GILLHAM TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL APR 5 1983

JAMES A. GILLHAM  
DISTRICT SUPERVISOR

shoe at 5,100'. WOC. Tag top of cement plug. Plug to be minimum 50' above casing shoe. Spot 78 barrels 10# brine with 25# gel/barrel. Run free point to determine the top of cement behind the 9-5/8" casing. Cut casing 1 jt above the top of cement. Pull casing. (Note: cement top at 3900' by temperature survey). Spot 100 sx class C neat across 9-5/8" casing cut point. WOC. Tag top of cement plug. If the plug is 50' above the 9-5/8" casing cut point proceed with brief. If not, spot more cement until the 50' requirement is met. Spot 277 barrels 10# brine with 25# gel/barrel. Spot 70 sx class C neat across the 20" casing shoe at 1882'. WOC. Tag top of cement plug. Plug to be minimum of 50' above casing shoe. Spot 280 barrels 10# brine with 25# gel/barrel. Spot 10 sx class C neat from 15' to surface. Weld on cap and erect permanent abandonment marker.  
\* Notify BLM prior to setting plugs.

RECEIVED  
APR 6 1983  
C.D.  
BLM OFFICE