

WORKOVER PROCEDURE

DATE: 3-14-89

WELL NO. & TYPE OF JOB: State 731 # 5 P&A

DRILLED & COMPLETED: 1982

LAST WO: 1984

FIELD: Jalmat COUNTY: Lea, New Mex

PREPARED BY: M.W. GORE

TD: 4050' PBD: 3849'

DATUM: _____

DIST RKB TO THF: _____

TUBINGHEAD: MAKE _____

SIZE _____

PRESSURE RATING _____

CASING INFORMATION:

	SIZE	WEIGHT	GRADE	SET @	SX CMT	TOC
SURFACE:	<u>8-5/8"</u>	<u>24</u>	<u>K-55</u>	<u>300'</u>	<u>200</u>	<u>0</u>
INTERMEDIATE:						
Production:	<u>5-1/2"</u>	<u>15.5</u>	<u>K-55</u>	<u>4050</u>	<u>750</u>	<u>0</u>

LINER: SIZE

WEIGHT

GRADE

TOP

BOTTOM

TOC

PRESENT PERFORATIONS & FORMATION:

Yates 7R

3887'-4003'

TUBING DATA: SIZE 2 3/8 WT. 4.7 GRADE J-55 THD. EUE BTMD @ 30

NO. OF JTS. 1

MISC. _____

PACKER & MISC.: CIBP @ 3849

PROCEDURE

1. WIRU PU. NU BOPE.
2. Pick up rental string of 2-3/8" tubing and GIH to 3849'. Test casing to 500 psig.
3. Circulate hole with GBW and spot plugs as follows:
 - 10 sacks @ 3849
 - 25 sacks @ 2150'
 - 50 sacks @ 350' (Circulate to surface)
4. LD tubing and ND BOPE. Cut off wellhead and WO dry hole marker.

NOTE: Notify NMOCD prior to commencing operations.

[Handwritten signature]
3-14-89

[Handwritten signature]
3-14-89