

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form E-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
State ☒ Non ☐
3. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT AND FORM C-101 FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
Sun Exploration & Production Company
3. Address of Operator
P.O. Box 1861, Midland, Texas 79702
4. Location of Well
UNIT LETTER A 1250 FEET FROM THE North LINE AND 1250 FEET FROM
THE East LINE, SECTION 8 TOWNSHIP 22-S RANGE 36-E NMPM.
10. Field and Pool, or Wellcat
Eunice Seven Rivers
Queen South
11. Elevation (Show whether DF, RT, GR, etc.)
3564.4' GR
12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐
TEMP. FAMILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐ OTHER ☐ CASING TEST AND CEMENT JOBS ☐
OTHER ☐ ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud 8-¹³21-83

R & C 14 Jts 8 5/8 Csg. Cs 579, BP 538, Hal cmts w/375 Sxs "C" w/2% CACL
& 1/4# Flocele/Sx, FP 200-300, Circ 75 Sxs Cmt. Test Csg & BOP 1000

8-18-83

R & C 94 Jts 5 1/2 17= K-55 8RD, St & C Csg. w/95 Scratchers & 22 Cmt,
CS 3900, FC 3867, DV Tool 2691/Howco proceed Cmt w/20 Bbls Mud Flush,
5 bbls 2% KCL, 20 bbls Flochek, 5 bbls 2% KCL, Drop BTM plug & 10 bbls
fresh wtr. Howco Cmt 1st stage w/300 Sxs "C" 50-50 Poz, 11% Salt, FP
500-1000, JC 1PM, Circ. 125 Sxs Cmt, Drop Bomb. Open DV tool recip pipe
thruout 1st stage, circ thru PV tool 5 hrs, NP BOP, set slips, weld on
nipple, pack off head/ Howco Cmt 2nd stage thru PV tool w/1000 Sxs "C"
Neat, holding 200 PSI back press on Csg. FP 800-2000, Close PV tool
final back on csg. 220 PSI to 425 Psi, left 425 PSI on Csg.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed [Signature] TITLE Sr. Acct. Asst. DATE 8-29-83

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

COPIES BY TITLE DATE SEP 2 1983

CONDITIONS OF APPROVAL, IF ANY: