STATE OF NEW MEXICO NERGY AND MINERALS DEPARTMENT	•
OIL CONSERVATION DIVISION	
SANTA FE	Form C-103
FILE SANTA FE, NEW MEXICO 87501	Revised 10-1-
U.S.G.S.	Sa. Indicate Type of Leuse
LAND OFFICE	State XX Fre
OPERATOR	5. Sigle Oil & Gas Lease No.
	St. State Off & Gus Ledge No.
SUNDRY NOTICES AND REPORTS ON WELLS (00 HOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DECEED OF PLUE DACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
	7. Unit Agreement Name
Vame of Operator	Eunice Monument South
Chevron U.S.A. Inc.	8. Farm or Lease Name Unit
Address of Operator	_
P.O. Boy 670 Unline Mr. 000/0	9. Well No.
P.O. Box 670, Hobbs, NM 88240	149
	10. Field and Pool, or Wildcat
UNIT LETTER H 2030 FEET FROM THE NOTTH LINE AND 760	Eunice Monument G/SA
THE East LINE, SECTION 31 TOWNSHIP 205 37E	
NMPK	
15. Elevation (Show whether DF, RT, GR, etc.)	
	12. County
Check Approxime D 21 + 11	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Of NOTICE OF INTENTION TO:	her Data
NOTICE OF INTENTION TO:	T REPORT OF:
RFORM REMEDIAL WORK	(
MPORARILY ABANDON	ALTERING CASING
CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENY
OTHER SQZ WER, reperf,	acdz —
OTHER	
Describe Proposed or Completed Operation (CL)	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In order to shut off the excessive water production, the following work was performed 6-23-87 through 8-2-87.

POH w/ prod tubing, Break circulation w/air, cleanout hydromite and sand plug f/3855 to 3900. GIH w/cmt retainer to 3707, pmp kill fluid thru retainer. Set retainer at 3707, test tbg to 3000psi. establish inj rate at 3 bpm, batch mix 100sx Class C, Tail w/200sx Class C, Displace w/ CKF. Stage sqz, held at 1310psi. rev out 21 sx, left 9sx in csg, 270 sx in formation. WOC. GIH and tag at 3701, Drill 5' cmt above retainer, tag retainer at 3706. Retainer and 29' cmt to 3735, GIH to 3735, Drill 90' cement f/3735-3825, Circulate clean. Test to 500psi, ok. RU and perf w/4" guns 2 JHPF, 120 deg. phased, 16 holes, 3784-86,3792-94,3803-05, 3817-19, acidized w/ 900 gallons 20% NEFE HCL. Swab.Run prod tubing & pmp equip, Left well SI 6-29- thru 7-30. 7-30-87 POH w/ rods, pmp, prod. equip. Perf 3646-50, 3696-3700, w/4" guns, 2 JHPF, 180 deg. phase, 16 holes. Acidize across perfs 3646-50, 3996-3700, w/1500 gallons 15% NEFE HCL. Swab. TIH w/ prod tbg, well tubed to 3672, ND BOP, NU WH, Run pmp and rods, space out, hang on beam. Load & test pmp action. Turn over to production.

ORIGINAL SIGNED BY JERRY SEXTON OVED BYDISTRICT I SUPERVISOR DITIONS OF APPROVAL, IF ANY:	SEP 2 2 1987
" AL Elme J/ R. E alking une Staff Drilling Engineer	Sept. 18, 1987
nereby certify that the information above is true and complete to the beat of my knowledge and belief.	