

Warren McKee Brine Well No. 2
P&A Procedure Outline

Well information is shown on the attached wellbore diagram.

1. Pull all production equipment from the well.
2. Set a CIBP @ 1550' MD (bottom of cased hole section - casing shoe @ 1580' MD) to isolate the open hole cavity from the wellbore.
3. RIH with open ended tubing and spot a minimum of a ~~35'~~ 200' cement plug on top of CIBP.
4. Fill casing with salt gel mud consisting of 10 pound brine with 25 pounds of gel per barrel.
5. Lay a minimum of a 100' cement plug at the 9-5/8" casing shoe @ 420' MD.
6. Fill casing with salt gel mud consisting of 10 pound brine with 25 pounds of gel per barrel.
7. Spot a surface plug with a minimum of 10 sacks.
8. Cut off the wellhead and erect a P&A marker.
9. Restore location as necessary.

NOTE: Should only need to tag the cement plug at the casing shoe.