(June 1990)	DEDADTMENT OF THE INTEDIOD 2: \$1	
	DEPARTMENT OF THE INTERIOR	
	BUREAU OF LAND MANAGEMENT	Expires: March 31, 1993 5. Lease Designation and Serial No.
	lob	bs, NM 0.241 LC 063458
	SUNDRY NOTICES AND REPORTS ON WELL	
Do not use this form for prop	cosals to drill or to deepen or reentry to a different	reservoir.
Use "APPLICATION	N FOR PERMIT " for such proposals	7. If Unit or CA, Agreement Designation
	SUBMIT IN TRIPLICATE	
1. Type of Well	INJECTION	
	INJECTION Xher	8 VName of lease & well Warren Unit Blin/Tubb WF
2. Name of Operator		Well #204
CONOCO, INC. 3. Address and Telephone No.		9. /api weil #
10 Dente Dr. Suite 10016/ Mi	idland Texas 79705-4500 9/5 686-5424 915 684-6381	30 025 33640 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., F		
Surface: 1330' FSL & 13	330' FWL Sec 34, T20S, R38E	Warren Blinebry Tubb Oil & Gas 11. County or Parish, State
TD: same as abov	/e	Lea, NM
12 CHECK APPROPRIA	ATE BOX(s) TO INDICATE NATURE OF NO	TICE, REPORT, OR OTHER DATA
TYPE OF SUBMIS	SION	TYPE OF ACTION
Notice of Intent	Abando	nment Change of Plans
	Recomp	New Construction
X Subsequent Repo	ort Plugging	g Back Non-Routine Fracturing
	Casing	Repair Water Shut-Off
Final Abandonme		
	X Scale squ	Jeeze, clean out Dispose Water (Note: Report results of multiple completion on Weil
		Completion or Recompletion Report and Log form.)
	rface locations and measured and true vertical depths for all markers	
12-4-98: Open up we test BOP, rel 12-7-98: Open up we latch onto Ri move plug to perf, pulled t 12-8-98: POOH w/ R l2-9-98: Finish going load & test -	ned well, worked pump free, POOH w/rods & ell, RU pump truck, tagged @ 6694', pulled p lease plug, POOH w/plug & tbg, RIH w/bit & s ell, RIH w/RBP & Pkr, RU pump truck, test lir	pump, kill well, ND wellhead, NU BOP, SION. bicked up RBP, run I jt. set plug, plug scrapper - POOH, SION. hes - acidize well, release pkr, RIH bove perfs, pump acid, release pkr, RIH-move luid level-3600', chemical squeeze bottom DOH, oaid down bailer, started in hole w/tbg. ad, RIH w/pump & rods, seat pump, n. , 2 3/8" @ 6684'.
12-4-98: Open up we test BOP, rel 12-7-98: Open up we latch onto RI move plug to perf, pulled t 12-8-98: POOH w/ R I2-9-98: Finish going load & test - Pulled 6683	ned well, worked pump free, POOH w/rods & ell, RU pump truck, tagged @ 6694', pulled p elease plug, POOH w/plug & tbg, RIH w/bit & ell, RIH w/RBP & Pkr, RU pump truck, test lin BP, pull plug to op of bottom perfs, set pkr al o below perfs, pull above, set pkr, run swab f to to perf chemical squeeze perf. SION. RBP & pkr, RIH w/bailer, cleaned to 6725', PO g in hole w/tbg, ND BOP, wet TAC NU wellhe check pump action, rig down - clean location '2 3/8" tubing, ran back in hole- SN @ 6662'	pump, kill well, ND wellhead, NU BOP, SION. sicked up RBP, run I jt. set plug, plug scrapper - POOH, SION. nes - acidize well, release pkr, RIH bove perfs, pump acid, release pkr, RIH-move luid level-3600', chemical squeeze bottom DOH, oaid down bailer, started in hole w/tbg. ad, RIH w/pump & rods, seat pump, n. , 2 3/8" @ 6684'.
12-4-98: Open up we test BOP, re 12-7-98: Open up we latch onto Ri move plug to perf, pulled t 12-8-98: POOH w/ R I2-9-98: Finish going load & test -	ned well, worked pump free, POOH w/rods & ell, RU pump truck, tagged @ 6694', pulled p elease plug, POOH w/plug & tbg, RIH w/bit & ell, RIH w/RBP & Pkr, RU pump truck, test lin BP, pull plug to op of bottom perfs, set pkr al o below perfs, pull above, set pkr, run swab f to to perf chemical squeeze perf. SION. RBP & pkr, RIH w/bailer, cleaned to 6725', PO g in hole w/tbg, ND BOP, wet TAC NU wellhe check pump action, rig down - clean location '2 3/8" tubing, ran back in hole- SN @ 6662'	pump, kill well, ND wellhead, NU BOP, SION. sicked up RBP, run I jt. set plug, plug scrapper - POOH, SION. nes - acidize well, release pkr, RIH bove perfs, pump acid, release pkr, RIH-move luid level-3600', chemical squeeze bottom DOH, oaid down bailer, started in hole w/tbg. ad, RIH w/pump & rods, seat pump, n. (ORIG. SGD.) DAVID R. GLASS
12-4-98: Open up we test BOP, rel 12-7-98: Open up we latch onto RI move plug to perf, pulled t 12-8-98: POOH w/ R I2-9-98: Finish going load & test - Pulled 6683'	ned well, worked pump free, POOH w/rods & ell, RU pump truck, tagged @ 6694', pulled p elease plug, POOH w/plug & tbg, RIH w/bit & s ell, RIH w/RBP & Pkr, RU pump truck, test lin BP, pull plug to op of bottom perfs, set pkr al o below perfs, pull above, set pkr, run swab f to to perf chemical squeeze perf. SION. RBP & pkr, RIH w/bailer, cleaned to 6725', PC g in hole w/tbg, ND BOP, wet TAC NU wellhe o check pump action, rig down - clean location ' 2 3/8" tubing, ran back in hole- SN @ 6662'.	pump, kill well, ND wellhead, NU BOP, SION. bicked up RBP, run I jt. set plug, plug scrapper - POOH, SION. hes - acidize well, release pkr, RIH bove perfs, pump acid, release pkr, RIH-move luid level-3600', chemical squeeze bottom DOH, oaid down bailer, started in hole w/tbg. ad, RIH w/pump & rods, seat pump, n. , 2 3/8" @ 6684'.
12-4-98: Open up we test BOP, rel 12-7-98: Open up we latch onto RI move plug to perf, pulled t 12-8-98: POOH w/ R 12-9-98: Finish going load & test - Pulled 6683'	ned well, worked pump free, POOH w/rods & ell, RU pump truck, tagged @ 6694', pulled p elease plug, POOH w/plug & tbg, RIH w/bit & ell, RIH w/RBP & Pkr, RU pump truck, test lin BP, pull plug to op of bottom perfs, set pkr al o below perfs, pull above, set pkr, run swab f to to perf chemical squeeze perf. SION. RBP & pkr, RIH w/bailer, cleaned to 6725', PO g in hole w/tbg, ND BOP, wet TAC NU wellhe check pump action, rig down - clean location t' 2 3/8" tubing, ran back in hole- SN @ 6662' Ann E Ritchie Title REGULATORY AGENT	pump, kill well, ND wellhead, NU BOP, SION. sicked up RBP, run I jt. set plug, plug scrapper - POOH, SION. nes - acidize well, release pkr, RIH bove perfs, pump acid, release pkr, RIH-move luid level-3600', chemical squeeze bottom DOH, oaid down bailer, started in hole w/tbg. ad, RIH w/pump & rods, seat pump, n. (ORIG. SGD.) DAVID R. GLASS
12-4-98: Open up we test BOP, rel 12-7-98: Open up we latch onto RI move plug to perf, pulled t 12-8-98: POOH w/ R 12-9-98: Finish going load & test - Pulled 6683'	ned well, worked pump free, POOH w/rods & ell, RU pump truck, tagged @ 6694', pulled p elease plug, POOH w/plug & tbg, RIH w/bit & ell, RIH w/RBP & Pkr, RU pump truck, test lin BP, pull plug to op of bottom perfs, set pkr al o below perfs, pull above, set pkr, run swab f to to perf chemical squeeze perf. SION. RBP & pkr, RIH w/bailer, cleaned to 6725', PO g in hole w/tbg, ND BOP, wet TAC NU wellhe check pump action, rig down - clean location t' 2 3/8" tubing, ran back in hole- SN @ 6662' Ann E Ritchie Title REGULATORY AGENT	pump, kill well, ND wellhead, NU BOP, SION. bicked up RBP, run I jt. set plug, plug scrapper - POOH, SION. hes - acidize well, release pkr, RIH bove perfs, pump acid, release pkr, RIH-move luid level-3600', chemical squeeze bottom DOH, oaid down bailer, started in hole w/tbg. ad, RIH w/pump & rods, seat pump, n. , 2 3/8" @ 6684'.

statements or representations as to any matter within its jurisdiction.

IC

-----