

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-6807

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Kaiser State
2. Name of Operator Hal J. Rasmussen Operating Inc.	8. Well No. 14
3. Address of Operator 6 Desta Dr. Ste. 2700, Midland Tex. 79705	9. Pool name or Wildcat Wilson Yates-Seven Rivers
4. Well Location Unit Letter <u>L</u> : <u>2310</u> Feet From The <u>South</u> Line and <u>990</u> Feet From The <u>West</u> Line Section <u>13</u> Township <u>21S</u> Range <u>34E</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3684

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
Work to commence 2-10-92

MIRU, POOH w/Pump and rods. Lower Tbg., Tag bottom and strap POOH. Run GR-NEU log TD to 3000'. TIH open ended to TD. Spot CMT TD to 3000'. POOH to 2000' and reverse out. Shut well in and pressure up to 500 PSI at Surf. and shut-in and WOC overnight. TIH with 6 1/8" bit, DC's and 2 7/8" tbg. drill out CMT to just below Yates. POOH. Run csg. scraper to PBTD and POOH. TIH with pkr to 100' above Yates and set. Test CSG. between Pkr and Cmt. to 2000 PSI. If CSG. leaks locate holes and determine perfs. accordingly. POOH. Perf Yates. TIH with Pkr., spot acid across perfs., ball out with acid. Sweep perfs and reset Pkr. Frac Yates with gelled water and 190,000# sand. Clean out with foam unit, DC's bit and ETC. to 3670'. POOH. Run pumping hook-up and set 1-2 joints above perfs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Scott Casey TITLE Agent DATE 1-30-92

TYPE OR PRINT NAME Scott Casey TELEPHONE NO. (915) 687-1664

(This space for State Use)

ORIGINAL SIGNED BY [Signature]

FEB 05 '92

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY: