

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-013
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC 031740-6

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Eunice Monument South I

8. FARM OR LEASE NAME

9. WELL NO.

210

10. FIELD AND POOL, OR WILDCAT

Eunice Monument GB/SA

11. SEC. T. R. M. OR BLK. AND
SURVEY OR AREA

Sec. 4, T21S, R36E

12. COUNTY OR PARISH 13. STATE

Lea NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Chevron U.S.A. Inc.

3. ADDRESS OF OPERATOR

P.O. Box 670, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

4670/S

3261 FNL and 1980 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, TO, OR, etc.)

3557'

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Sqz off water

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

XX

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work performed: 12-12- 12-19-88 TD: 3870 PB: 3766

POOH w/production equip. Set pkr at 3813', test to 750psi, ok. Release pkr, set CICR at 3766'. Batch mix 100sx C1 C. Pmp down tbg at 2 bpm. Pmp all cmt, shut down. WOC 22 hrs. TIH, tag cmt at 2590'. Establish circ. Drill out cmt 2590' to 3461', to CICR at 3756'. Circulate clean. Perf 3752'-60, 3734-44, 3721-28, 3690-3714, 3650-74, total 73 holes. w/2" guns, 1 JHPF, 180°, circulate hole clean. Spot 15% NEFE across perfs, 3650- 3760. Press annulus to 4000psi, ok. Acidize perfs w/1725 gallons 15% NEFE acid. Swab. TIH w/prod. tbg. ND BOP, NUWH. Run prod. equip. Space out, hang on. Turn over to production.

18. I hereby certify that the foregoing is true and correct

SIGNED L. J. Elmore

TITLE Technical Assistant

DATE 1-5-89

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

ACCEPTED FOR RECORD
DATE _____

JAN 19 1989

*See Instructions on Reverse Side

SJS

CARLSBAD, NEW MEXICO

RECEIVED

JAN 20 1980

OCB
HODS OFF